Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
WON KIM
SURFSIDE RESORT MOTEL - POOL
101 NW 11TH
ROCKAWAY, OR 97136

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2940013A Area: 60
Units: 0
County: 29

SURFSIDE RESORT MOTEL - POOL
PO BOX 1055
MANZANITA, OR 97130

Phone: (503) 355-2312 x
Inspector: Annette Pampush
Start Date/Time: 2/7/2017 at 12:38:57 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THIS IS A RECHECK INSPECTION. TWO DAYS AGO I TALKED WITH OPERATOR AND POOL WAS STILL AT 10 PPM FREE CHLORINE. I TOLD HIM HE NEEDS TO GET IT DOWN TO 5. HE WAS GOING TO CLOSE THE POOL AND ADD SODIUM THIOSULFITE TO LOWER THE CONC. THIS IS A RECHECK . CHLORINE IS NOW 1.0 PPM, THEY ARE SLOWLY RAISING THE LEVEL

Free Chlorine (0.8-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(F):
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (0-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

Comments:

Site Report Generated: 6/23/2017 4:22:37 PM

Person In Charge Inspection By: Annette Pampush

Historical 1/26/2017 **POOL PROGRAM INSPECTION REPORT**

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
WON KIM
SURFSIDE RESORT MOTEL - POOL
101 NW 11TH
ROCKAWAY, OR 97136

Inspection Type: SEMI
Inspection Result: CLOSE
Establishment #: 2940013A Area: 60
Units: 0
County: 29

SURFSIDE RESORT MOTEL - POOL
PO BOX 1055
MANZANITA, OR 97130

Phone: (503) 355-2312 x
Inspector: Jaime Craig
Start Date/Time: 1/26/2017 at 1:16:07 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

DOOR LOCKED
SIGNS AVAILABLE
RECORDS KEPT
LADDERS AND HANDRAILS ALL SECURED

Free Chlorine (0.8-5.0 ppm):	12.	Bromine (3.0-8.0 ppm):		Temperature(F):	90
Combined Chlorine (0-.5 ppm):	.6	Cyanuric Acid (0-150 ppm):		Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	60	Hardness (175-400 ppm):	170	pH (7.2-7.6):	7.4
Inlet Pressure:		Outlet Pressure:	20	Flow Rate:	55

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-060-0200(1.01)

VIOLATION OF OAR 333-060-0200 (1) The free chlorine residual in the pool is less than 0.8 ppm (0.8 mg/kg) or greater than 5.0 ppm (5 mg / kg). Specifically:

CHLORINE AT 12

Maintain the free chlorine residual within the range set out in the pool Water Quality Parameters, OAR 333-060-0200 and Table 3; ideal range being 1.0 to 3.0 ppm (1 to 3 mg / kg) free chlorine.

A wading pool must comply with OAR 333-060-0515 (1).

POOL COSED UNTIL LOWERED TO ACCEPTABLE RANGE

333-060-0200(3)(4)

VIOLATION OF OAR 333-060-0200 (3) & (4) The pool water quality parameters are not tested at the required frequencies or are not recorded.

CALCIUM HARDNESS SHOULD BE TESTED WEEKLY.

Complete and record the required pool water tests at the minimum frequencies as described in OAR 333-060-0200 (3)(a) to (3)(j), or as required by the Division or local public health authority.

333-060-0210(3)(a)

VIOLATION OF OAR 333-060-0210 (3)(a) The pool does not have a lifehook.

POLE AVALIBLE BUT NO HOOK ATTACHED TO POLE

Provide a lifehook (shepherd's crook) in the pool area. Wading pools and spas do not require a lifehook. The lifehook has a crook design and is attached to a non-telescoping pole between 8 - 16 feet long. The pole must be sized to be useable in the int

HOOK NEEDS TO BE AVAILABLE AT ALL TIMES.

333-060-0210(7)

VIOLATION OF OAR 333-060-0210 (7) There are doors, gates or windows that are not maintained so as to be lockable, or the pool is not properly secured when not in use.

WINDOW OPENS WIDE ENOUGH FOR CHILD TO ACCESS FROM OUTSIDE

Provide and maintain hardware on all doors, gates and windows so they operate properly and the pool can be secured when not in use. Secure the pool whenever the pool is not open for use.

SECURE SO DOES NOT OPEN FULLY. TALKED WITH MAINTENANCE STAFF ABOUT OPTIONS. CORRECTED

Comments:

Site Report Generated: 6/23/2017 4:22:38 PM

Person In Charge Inspection By: Jaime Craig

Historical 3/29/2016 **POOL PROGRAM INSPECTION REPORT** Page 4 of 13

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
WON KIM
SURFSIDE RESORT MOTEL - POOL
101 NW 11TH
ROCKAWAY, OR 97136

SURFSIDE RESORT MOTEL - POOL
PO BOX 1055
MANZANITA, OR 97130

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2940013A Area: 60
Units: 0
County: 29
Phone: (503) 355-2312 x
Inspector: Mason Lyman
Start Date/Time: 3/29/2016 at 12:44:28 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SEMIANNUAL INSPECTION OF FACILITY-

SKIMMERS OK
GATES/DOORS OK
STAIRS/LADDERS OK
SAFETY EQUIPMENT OK
SIGNS OK
PHONE AVAILABLE

Free Chlorine (0.8-5.0 ppm):	**3.6**	Bromine (3.0-8.0 ppm):		Temperature(F):	**71**
Combined Chlorine (0-.5 ppm):	**0.0**	Cyanuric Acid (0-150 ppm):	**0**	Clarity (Y/N):	**Y**
Total Alkalinity (80-200 ppm):	**80**	Hardness (175-400 ppm):	**140**	pH (7.2-7.6):	**7.2**
Inlet Pressure:		Outlet Pressure:		Flow Rate:	**55**

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

**CONSIDER PUTTING ON RECORD FORMS TO PUT AMOUNT OF WHICH CHEMICALS WHEN PUTTING IN POOL.
ALSO, RECORD READING OF CHLORINE FROM THE AFTERNOON ON FORMS AS WELL.
RECOMMEND GETTING A SCALE TO ACCURATELY DETERMINE CHEMICALS PUTTING INTO POOL.
**CHECK MAIN DRAIN FOR HOW LONG ITS BEEN INSTALLED. MAY NEED TO BE REPLACED.

Site Report Generated: 6/23/2017 4:22:38 PM

Person In Charge

Inspection By: Mason Lyman

Historical 9/23/2015 **POOL PROGRAM INSPECTION REPORT**

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
WON KIM
SURFSIDE RESORT MOTEL - POOL
101 NW 11TH
ROCKAWAY, OR 97136

SURFSIDE RESORT MOTEL - POOL
PO BOX 1055
MANZANITA, OR 97130

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2940013A Area: 60
Units: 0
County: 29
Phone: (503) 355-2312 x
Inspector: Mason Lyman
Start Date/Time: 9/23/2015 at 12:26:50 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

REGULAR SEMIANNUAL INSPECTION OF POOL-

Free Chlorine (0.8-5.0 ppm):	3.8	Bromine (3.0-8.0 ppm):		Temperature(F):	88
Combined Chlorine (0-.5 ppm):	0.4	Cyanuric Acid (0-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	90	Hardness (175-400 ppm):	240	pH (7.2-7.6):	7.4
Inlet Pressure:		Outlet Pressure:		Flow Rate:	40

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-060-0200(3)(4)

VIOLATION OF OAR 333-060-0200 (3) & (4) The pool water quality parameters are not tested at the required frequencies or are not recorded.

ONLY CHECKING COMBINED CHLORINE ONCE A DAY.

Complete and record the required pool water tests at the minimum frequencies as described in OAR 333-060-0200 (3)(a) to (3)(j), or as required by the Division or local public health authority.

CHECK COMBINED CHLORINE WHENEVER CHECKING FREE CHLORINE. SPOT WAS MADE ON RECORD SHEET FOR IT. RECORD ON SHEET WHEN AND HOW MUCH OF EACH CHEMICAL ADDED ON RECORD SHEET.

**HAVE PIC FIGURE OUT POOL SIZE IN GALLONS.
**RECOMMEND FACILITY GETTING SCALE TO ACCURATELY DETERMINE AMOUNTS OF CHEMICALS BEING ADDED.
**RECOMMEND SWITCHING FROM COLOR TO TITRATION CHLORINE TEST. TALKED TO PIC ABOUT DIFFERENCES.
**CHECK MAIN DRAIN PAPERWORK FOR COMPLIANCE WITH VGB LAW, AND REPLACE IF NEEDED WHEN DRAINING POOL IN A FEW WEEKS.

Site Report Generated: 6/23/2017 4:22:38 PM

Person In Charge

Inspection By: Mason Lyman

Historical 2/19/2015 **POOL PROGRAM INSPECTION REPORT** Page 8 of 13

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
WON KIM
SURFSIDE RESORT MOTEL - POOL
101 NW 11TH
ROCKAWAY, OR 97136

SURFSIDE RESORT MOTEL - POOL
PO BOX 1055
MANZANITA, OR 97130

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2940013A Area: 60
Units: 0
County: 29
Phone: (503) 355-2312 x
Inspector: Mason Lyman
Start Date/Time: 2/19/2015 at 2:13:18 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SCOOP FOUND TO OBTAIN ACCURATE MEASUREMENTS FOR ADDING CHEMICALS TO POOL.

LABEL WAS CORRECTED ON ITEM IN THE BACK, TO HELP OPERATORS WITH KNOWING WHAT IS AND ISN"T MEANT FOR EACH CHEMICAL.

ALKALINITY NOW AT 90 PPM. WITHIN GIVEN PARAMETERS.

POOL IS NOW OPEN

Free Chlorine (0.8-5.0 ppm):	**6.0**	Bromine (3.0-8.0 ppm):		Temperature(F):	**86**
Combined Chlorine (0-.5 ppm):	**.2**	Cyanuric Acid (0-150 ppm):	**0**	Clarity (Y/N):	**Y**
Total Alkalinity (80-200 ppm):	**90**	Hardness (175-400 ppm):	**250**	pH (7.2-7.6):	**7.2**
Inlet Pressure:		Outlet Pressure:		Flow Rate:	**40**
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Comments:

Site Report Generated: 6/23/2017 4:22:38 PM

Person In Charge Inspection By: Mason Lyman

Historical 2/19/2015 **POOL PROGRAM INSPECTION REPORT** Page 9 of 13

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
WON KIM
SURFSIDE RESORT MOTEL - POOL
101 NW 11TH
ROCKAWAY, OR 97136

SURFSIDE RESORT MOTEL - POOL
PO BOX 1055
MANZANITA, OR 97130

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2940013A Area: 60
Units: 0
County: 29
Phone: (503) 355-2312 x
Inspector: Mason Lyman
Start Date/Time: 2/19/2015 at 2:00:14 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

Comments:

Free Chlorine (0.8-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(F):
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (0-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

Comments:

Site Report Generated: 6/23/2017 4:22:38 PM

Person In Charge Inspection By: Mason Lyman

Historical 2/18/2015 **POOL PROGRAM INSPECTION REPORT** Page 10 of 13

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
WON KIM
SURFSIDE RESORT MOTEL - POOL
101 NW 11TH
ROCKAWAY, OR 97136

SURFSIDE RESORT MOTEL - POOL
PO BOX 1055
MANZANITA, OR 97130

Inspection Type: SEMI
Inspection Result: CONTIN
Establishment #: 2940013A Area: 60
Units: 0
County: 29
Phone: (503) 355-2312 x
Inspector: Mason Lyman
Start Date/Time: 2/18/2015 at 2:36:45 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SKIMMERS OK
STAIRS/LADDERS OK
SAFETY EQUIPMENT OK
SAFETY SIGNS/ RULES AND POOL PHONE SIGN ARE UP
TURNOVER OF POOL IS UNDER 8 HOURS.
RECORDS AND TESTING FREQUENCY IS GOOD, PLEASE DOCUMENT HOW MUCH OF EACH CHEMICAL YOU ADD EACH TIME FOR A MORE FULL RECORD.

**PLEASE OBTAIN A SCALE OR OTHER MEASURING DEVICE TO KNOW HOW MUCH OF EACH CHEMICAL IS BEING PUT INTO THE POOL.

**NOT RECOMMENDED TO BACKWASH SAND FILTER EVERYDAY. BACKWASH AFTER A 8-10 PSI PRESSURE INCREASE AT SAND FILTER. DIRTY FILTERS CLEAN BETTER THAN CLEAN FILTERS.

Free Chlorine (0.8-5.0 ppm):	6.0	Bromine (3.0-8.0 ppm):		Temperature(F):	87
Combined Chlorine (0-.5 ppm):	.2	Cyanuric Acid (0-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	60	Hardness (175-400 ppm):	300	pH (7.2-7.6):	7.2
Inlet Pressure:		Outlet Pressure:		Flow Rate:	40

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-060-0200(1.09)

VIOLATION OF OAR 333-060-0200 (1) The total alkalinity is less than 80 ppm or greater than 200 ppm. Specifically:

ALKALINITY AT 60 PPM.

Maintain the total alkalinity within the range set out in the pool Water Quality Parameters, OAR 333-060-0200 and Table 3, ideal being approximately 80 - 125 ppm total alkalinity. Most modern pool finishes are durable within this range as long as the cal

TALKED TO PIC. PLEASE ADD 9.3 POUNDS OF SODIUM BICARBONATE TO POOL TO CORRECT ALKALINITY VALUE.

Comments:

Site Report Generated: 6/23/2017 4:22:38 PM

Inspection By: Mason Lyman

Historical 8/27/2014 **POOL PROGRAM INSPECTION REPORT** Page 12 of 13

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
WON KIM
SURFSIDE RESORT MOTEL - POOL
101 NW 11TH
ROCKAWAY, OR 97136

SURFSIDE RESORT MOTEL - POOL
PO BOX 1055
MANZANITA, OR 97130

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2940013A Area: 60
Units: 0
County: 29
Phone: (503) 355-2312 x
Inspector: Mason Lyman
Start Date/Time: 8/27/2014 at 4:04:30 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

DOOK SELF CLOSES
FENCES/WALL OK
GOOO LOG BOOK
MECHANICAL ROOK OK
TEST KIT AVAILABLE
GOOD TESTING TECHNIQUE OBSERVED
CLARITY OK
DECK SURFACE OK
ENCLOSURE OK
SAFETY EQUIPMENT OK
VENTILATION WORKS AND IS ON

**COMBINED CHLORINE IS HIGH, SHOCK POOL OR CHANGE OUT WATER TO REDUCE NUMBER.

**EMPLOYEE SAYS THEY BACKWASH FILTERS EVERYDAY, RECOMMENDED TO BACKWASH MORE INFREQUENTLY AT RECOMMENDED PRESSURE TO INCREASE LIFE OF SAND FILTERS.

Free Chlorine (0.8-5.0 ppm):	4.8	Bromine (3.0-8.0 ppm):		Temperature(F):	86
Combined Chlorine (0-.5 ppm):	1.2	Cyanuric Acid (0-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	80	Hardness (175-400 ppm):	390	pH (7.2-7.6):	7.6
Inlet Pressure:		Outlet Pressure:		Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-060-0210(2)

VIOLATION OF OAR 333-060-0210 (2) No telephone, or other acceptable means to reach emergency assistance is accessible, or directions to the telephone are not provided.

NO EMER PHONE ON SITE

Provide a telephone that is accessible at all times the pool is open. The telephone must be capable of reaching emergency assistance without the use of coins or cards. Conspicuously post the location of the phone in the pool area.

The phone should b

PROVIDE PHONE OR DIRECTIONS TO PHONE AVIALABLE DURING ALL SWIMMING HOURS WITH EMERGENCY INFORMATION.

Comments:

Site Report Generated: 6/23/2017 4:22:38 PM

Person In Charge Inspection By: Mason Lyman