

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:

TILLAMOOK LODGING LIMITED PARTNERSHIP

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER RD

TILLAMOOK, OR 97141

Inspection Type: REINSP

Inspection Result: COMPLD

Establishment #: 2950003A Area: 62

Units: 0

County: 29

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER

TILLAMOOK, OR 97141

Phone: (503) 842-7599 x

Inspector: Mason Lyman

Start Date/Time: 2/4/2016 at 11:26:11 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

FLOW METER IS FIXED AT POOL- NEEDS TO BE ABOVE 36 GPM, IS AT 50 GPM.

CHEMISTRY LOOKS GOOD. GAVE RECOMMENDATION ON AIR HUMIDITY (AROUND 50%) AND AIR TEMPERATURE. PLEASE PROVIDE FAN ON CORNER OF HOT TUB DURING SHOCKING TO MOVE THE AIR AROUND BETTER, AND REMOVE COMBINED CHLORINE MORE EFFICIENTLY.

STILL WORKING ON THE SHOWER BY THE SPA.

Free Chlorine (1.5-5.0 ppm):	3.4	Bromine (3.0-8.0 ppm):		Temperature(Max)	102
Combined Chlorine (0-.5 ppm):	.3	Cyanuric Acid (30-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	130	Hardness (175-400 ppm):	340	pH (7.2-7.6):	7.2
Inlet Pressure:		Outlet Pressure:		Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

READY TO OPEN

Site Report Generated: 6/23/2017 2:29:01 PM

Person In Charge

Inspection By: Mason Lyman

Historical 2/1/2016

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

TILLAMOOK LODGING LIMITED PARTNERSHIP

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER RD

TILLAMOOK, OR 97141

Inspection Type: SEMI

Inspection Result: CONTIN

Establishment #: 2950003A Area: 62

Units: 0

County: 29

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER

TILLAMOOK, OR 97141

Phone: (503) 842-7599 x

Inspector: Mason Lyman

Start Date/Time: 2/1/2016 at 11:36:55 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

LADDERS OK
CLARITY IS GOOD
NEW PAINT ON BOTTOM
SKIMMERS OK
RULES OK
PHONE OK

Free Chlorine (1.5-5.0 ppm):	0.6	Bromine (3.0-8.0 ppm):		Temperature(Max)	102
Combined Chlorine (0-.5 ppm):	0.4	Cyanuric Acid (30-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	160	Hardness (175-400 ppm):	80	pH (7.2-7.6):	7.3
Inlet Pressure:		Outlet Pressure:		Flow Rate:	0

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-062-0165(1.11)

VIOLATION OF OAR 333-062-0165 (1) The calcium hardness is less than 100 ppm, specifically:

HARDNESS OF WATER AT 80 PPM.

The recommended minimum level of calcium hardness is 200 ppm, per OAR 333-062-0165 and Table 1. Low calcium hardness can cause aggressive corrosion, particularly in the heater. The pool should be maintained with the calcium demand fully saturated, but n

PLEASE CORRECT TO WITHIN 150-400.

333-062-0165(3)

VIOLATION OF OAR 333-062-0165 (3) The spa pool water quality parameters are not being tested at the required frequencies or are not recorded, specifically:

FACILITY IS TESTING WATER CHEMISTRY AT 8AM, AND NOON.

Complete and record the required spa pool water tests at the minimum frequencies as described in OAR 333-62-165(3)(a) through (i).

PLEASE TEST FREE CHLORINE/COMBINED CHLORINE AT 4PM AND 8PM INTERVAL.

Inspection Type: SEMI

Start Date/Time: 2/1/2016 at 11:36:55

333-062-0255(1)

VIOLATION OF OAR 333-062-0255(1) The spa pool meets one or more of the closure criteria. The spa pool license holder, operator, or responsible supervisor is responsible for closing the pool.

The spa pool has been closed by the appropriate pool staff, while they eliminate the reason for the spa pool closure in accordance with OAR 333-062-0255(3). When the reason for the closure is eliminated, the spa pool may reopen. THE POOL STAFF HAS ACTED

333-062-0255(3)(a)

VIOLATION OF OAR 333-062-0255 (3)(a) The disinfectant level does not meet the parameters in OAR 333-062-0170 (1), or items (a) thru (c) of Table 1.

FREE CHLORINE IN SPA IS 0.6 PPM. SPA CLOSED BY STAFF AT BEGINNING OF INSPECTION.

The minimum residual for free chlorine is 1.5 ppm and the maximum is 5 ppm for spas. Consistent maintenance of an ORP of 750 mv. or higher, while maintaining the free chlorine with in the correct ppm range, can allow the operator to reduce the manual tes

SPA CLOSED. PLEASE KEEP CONCENTRATION OF FREE CHLORINE BETWEEN 1.5 -10 PPM. PLEASE CALL OFFICE AT 503-842-3909 WHEN READY TO OPEN.

**TALKED TO STAFF ABOUT ABOUT HIGH HUMIDITY IN AIR (RECOMMEND BETWEEN 40-60%). MENTIONED TO CLEAN AROUND WINDOW SILLS TO PREVENT MOLD/MILDEW ACCUMULATION.

Site Report Generated: 6/23/2017 2:29:02 PM

Person In Charge

Inspection By: Mason Lyman

Page 3

Establishment: 2950003A
Inspection Type: REINSP

Page 4 of 17
Start Date/Time: 7/29/2015 at 12:32:55

Historical 7/29/2015

SPA INSPECTION REPORT

Page 4 of 17

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
TILLAMOOK LODGING LIMITED PARTNERSHIP
ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER RD
TILLAMOOK, OR 97141

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2950003A Area: 62
Units: 0
County: 29

ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER
TILLAMOOK, OR 97141

Phone: (503) 842-7599 x
Inspector: Mason Lyman

Start Date/Time: 7/29/2015 at 12:32:55 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

REINSPECTION OF SPA-

BETTER RECORDS

ALL CHEMISTRY UNDER CONTROL, AND READY TO OPEN.

FIXED FLOW METER, NOW OPERATING.

SCALE OBTAINED, NOW CAN ACCURATELY MEASURE CHEMICAL ADDITIONS TO POOL.

Free Chlorine (1.5-5.0 ppm):	2.4	Bromine (3.0-8.0 ppm):	Temperature(Max	101	
Combined Chlorine (0-.5 ppm):	.4	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y	
Total Alkalinity (80-200 ppm):	90	Hardness (175-400 ppm):	260	pH (7.2-7.6):	7.2
Inlet Pressure:		Outlet Pressure:		Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Comments:

Site Report Generated: 6/23/2017 2:29:02 PM

Person In Charge

Inspection By: Mason Lyman

Page 4

Historical 7/27/2015

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

TILLAMOOK LODGING LIMITED PARTNERSHIP

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER RD

TILLAMOOK, OR 97141

Inspection Type: SEMI

Inspection Result: CONTIN

Establishment #: 2950003A Area: 62

Units: 0

County: 29

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER

TILLAMOOK, OR 97141

Phone: (503) 842-7599 x

Inspector: Mason Lyman

Start Date/Time: 7/27/2015 at 3:30:45 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

INSPECTION OF SPA-

****FLOWMETER NEEDS TO BE WORKING.**

NEW HEATER FOR BOTH POOL AND SPA.

REPAINTED INSIDE OF SPA

SIGNS GOOD

****CONSIDER INCLUDING IN RECORDS THE AMOUNT OF CHEMICALS ADDED EACH TIME THEY ARE ADDED.**

Free Chlorine (1.5-5.0 ppm):	0.4	Bromine (3.0-8.0 ppm):		Temperature(Max)	103
Combined Chlorine (0-.5 ppm):	0.4	Cyanuric Acid (30-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	60	Hardness (175-400 ppm):	120	pH (7.2-7.6):	7.0
Inlet Pressure:		Outlet Pressure:		Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-062-0165(1.9)

VIOLATION OF OAR 333-062-0165 (1) The total alkalinity level does not comply with required water quality parameters. Specifically:

ALKALINITY AT 60 PPM

Maintain the total alkalinity level greater than 80 ppm and less than 175 ppm, the ideal range being 80-125 ppm. Most modern finishes are durable within this range as long as the calcium saturation is maintained and the water is balanced.

PLEASE INCREASE TO ABOVE 80 PPM.

333-062-0165(3)

VIOLATION OF OAR 333-062-0165 (3) The spa pool water quality parameters are not being tested at the required frequencies or are not recorded, specifically:

NOBODY MONITORING WATER CHEMISTRY FROM 3PM TO 10 PM.

Complete and record the required spa pool water tests at the minimum frequencies as described in OAR 333-62-165(3)(a) through (i).

PLEASE FOLLOW TESTING FREQUENCY GIVEN TO POOL PERSONNEL.

Inspection Type: SEMI

Start Date/Time: 7/27/2015 at 3:30:45

333-062-0255(1)

VIOLATION OF OAR 333-062-0255(1) The spa pool meets one or more of the closure criteria. The spa pool license holder, operator, or responsible supervisor is responsible for closing the pool.

The spa pool has been closed by the appropriate pool staff, while they eliminate the reason for the spa pool closure in accordance with OAR 333-062-0255(3). When the reason for the closure is eliminated, the spa pool may reopen. THE POOL STAFF HAS ACTED

333-062-0255(3)(a)

VIOLATION OF OAR 333-062-0255 (3)(a) The disinfectant level does not meet the parameters in OAR 333-062-0170 (1), or items (a) thru (c) of Table 1.

FREE CHLORINE AT 0.4 PPM

The minimum residual for free chlorine is 1.5 ppm and the maximum is 5 ppm for spas. Consistent maintenance of an ORP of 750 mv. or higher, while maintaining the free chlorine with in the correct ppm range, can allow the operator to reduce the manual tes

SPA CLOSED. CURRENTLY SHOCKING THE SPA. PLEASE STAY CLOSED UNTIL COMPLAINE IN REACHED IN ALL POOL CHEMISTRY PARAMETERS.

Comments:

Site Report Generated: 6/23/2017 2:29:02 PM

Person In Charge

Inspection By: Mason Lyman

Historical 1/7/2015 SPA INSPECTION REPORT Page 7 of 17

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
TILLAMOOK LODGING LIMITED PARTNERSHIP
ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER RD
TILLAMOOK, OR 97141

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2950003A Area: 62
Units: 0
County: 29

ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER
TILLAMOOK, OR 97141

Phone: (503) 842-7599 x
Inspector: Mason Lyman

Start Date/Time: 1/7/2015 at 1:45:58 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SATURATION INDEX FOR SPA AND 0.3, SLIGHTLY SCALING WATER, BUT OK.

****SPA READY TO BE REOPENED. BUT FACILITY IS KEEPING SPA/POOL AREA CLOSED UNTIL SUPERCHLORINATION CYCLE IS COMPLETE, AND AFTER ADDING ALKALINITY AND HARDNESS INCREASER.**

Free Chlorine (1.5-5.0 ppm):	6.2	Bromine (3.0-8.0 ppm):	Temperature(Max	99
Combined Chlorine (0-.5 ppm):	.2	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	100	Hardness (175-400 ppm):	pH (7.2-7.6):	7.7
Inlet Pressure:		Outlet Pressure:	Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

Comments:

Site Report Generated: 6/23/2017 2:29:02 PM

Person In Charge

Inspection By: Mason Lyman

Page 7

Historical 1/6/2015

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

TILLAMOOK LODGING LIMITED PARTNERSHIP

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER RD

TILLAMOOK, OR 97141

Inspection Type: SEMI

Inspection Result: CONTIN

Establishment #: 2950003A Area: 62

Units: 0

County: 29

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER

TILLAMOOK, OR 97141

Phone: (503) 842-7599 x

Inspector: Mason Lyman

Start Date/Time: 1/6/2015 at 2:04:19 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SKIMMERS OK

SIGNS/LADDERS/DESK SURFACES ALL CLEAR AND WORKING

DATE TESTING CHEMICALS AND REPLACE WHEN WORN.

GOOD RECORD KEEPING, KEEP RECORDS FOR AT LEAST 2 YEARS.

SATURATION INDEX FOR SPA IS -0.4

Free Chlorine (1.5-5.0 ppm):	.4	Bromine (3.0-8.0 ppm):	Temperature(Max)	102
Combined Chlorine (0-.5 ppm):	.7	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	90	Hardness (175-400 ppm):	pH (7.2-7.6):	7.3
Inlet Pressure:		Outlet Pressure:	Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

333-062-0165(1.11)

VIOLATION OF OAR 333-062-0165 (1) The calcium hardness is less than 100 ppm, specifically:

CALCIUM HARDNESS MEASURED AT 110 PPM.

The recommended minimum level of calcium hardness is 200 ppm, per OAR 333-062-0165 and Table 1. Low calcium hardness can cause aggressive corrosion, particularly in the heater. The pool should be maintained with the calcium demand fully saturated, but n

PLEASE CORRECT.

333-062-0165(1.3)

VIOLATION OF OAR 333-062-0165 (1) The combined chlorine (chloramine) is greater than 0.5 ppm (0.5 mg / kg). Specifically:

COMBINED CHLORINE MEASURED AT 0.7 PPM.

Maintain the combined chlorine (chloramine) residual within the range set out in spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 0 ppm, measured combined chlorine. Combined chlorine (chloramines) is irritating to swimmers and

KEEP COMBINED CHLORINE BELOW 0.5 PPM DURING HOURS OF OPERATION.

333-062-0255(1)

VIOLATION OF OAR 333-062-0255(1) The spa pool meets one or more of the closure criteria. The spa pool license holder, operator, or responsible supervisor is responsible for closing the pool.

The spa pool has been closed by the appropriate pool staff, while they eliminate the reason for the spa pool closure in accordance with OAR 333-062-0255(3). When the reason for the closure is eliminated, the spa pool may reopen. THE POOL STAFF HAS ACTED

333-062-0255(3)(a)

VIOLATION OF OAR 333-062-0255 (3)(a) The disinfectant level does not meet the parameters in OAR 333-062-0170 (1), or items (a) thru (c) of Table 1.

FREE AVAILABLE CHLORINE MEASURED AT ONLY 0.4 PPM.

The minimum residual for free chlorine is 1.5 ppm and the maximum is 5 ppm for spas. Consistent maintenance of an ORP of 750 mv. or higher, while maintaining the free chlorine with in the correct ppm range, can allow the operator to reduce the manual tes

PLEASE CORRECT.

Comments:

Site Report Generated: 6/23/2017 2:29:02 PM

Person In Charge

Inspection By: Mason Lyman

Page 9

Historical 7/23/2014

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

TILLAMOOK LODGING LIMITED PARTNERSHIP

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER RD

TILLAMOOK, OR 97141

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2950003A Area: 62

Units: 0

County: 29

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER

TILLAMOOK, OR 97141

Phone: (503) 842-7599 x

Inspector: Mason Lyman

Start Date/Time: 7/23/2014 at 10:18:29 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

OPERATOR IS CHANGING OUT FILTER CURRENTLY.
SAFETY EQUIPEMTN GOOD, AND SIGNS AVAILABLE.
SEE COMMENT ON POOL INSPECTION ABOUT PROPER PHONE USE AND SET UP.

Free Chlorine (1.5-5.0 ppm):	2.4	Bromine (3.0-8.0 ppm):	Temperature(Max	102	
Combined Chlorine (0-.5 ppm):	.6	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y	
Total Alkalinity (80-200 ppm):	30	Hardness (175-400 ppm):	180	pH (7.2-7.6):	7.2
Inlet Pressure:		Outlet Pressure:		Flow Rate:	65
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-062-0165(1.3)

VIOLATION OF OAR 333-062-0165 (1) The combined chlorine (chloramine) is greater than 0.5 ppm (0.5 mg / kg). Specifically:

COMBINED CHLORINE READING AT 0.6 PPM.

Maintain the combined chlorine (chloramine) residual within the range set out in spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 0 ppm, measured combined chlorine. Combined chlorine (chloramines) is irritating to swimmers and

AIR TEMPERATURE OF THE ENCLOSURE FOR INDOOR POOL WAS BETWEEN 95-96F.

Site Report Generated: 6/23/2017 2:29:02 PM

Establishment: 2950003A
Inspection Type: REINSP

Page 11 of 17
Start Date/Time: 11/8/2013 at 9:24:09

Historical 11/8/2013

SPA INSPECTION REPORT

Page 11 of 17

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
TILLAMOOK LODGING LIMITED PARTNERSHIP
ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER RD
TILLAMOOK, OR 97141

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2950003A Area: 62
Units: 0
County: 29

ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER
TILLAMOOK, OR 97141

Phone: (503) 842-7599 x
Inspector: Melissa Kauffman

Start Date/Time: 11/8/2013 at 9:24:09 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A REINSPECTION

SPA CHEMISTRY IS BALANCED
FLOW METERS HAVE BEEN REPAIRED
DISCUSSED HOW TO CALCULATE A PROPER TURNOVER RATE
DISCUSSED CHEMICLE SAMPLING TECHNIQUES

Free Chlorine (1.5-5.0 ppm):	3.9	Bromine (3.0-8.0 ppm):		Temperature(Max	101
Combined Chlorine (0-.5 ppm):	.1	Cyanuric Acid (30-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	50	Hardness (175-400 ppm):	70	pH (7.2-7.6):	7.0
Inlet Pressure:		Outlet Pressure:		Flow Rate:	75
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Comments:

Site Report Generated: 6/23/2017 2:29:02 PM

Inspection By: Melissa Kauffman

Page 11

Historical 11/7/2013

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

TILLAMOOK LODGING LIMITED PARTNERSHIP

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER RD

TILLAMOOK, OR 97141

Inspection Type: SEMI

Inspection Result: CLOSE

Establishment #: 2950003A Area: 62

Units: 0

County: 29

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER

TILLAMOOK, OR 97141

Phone: (503) 842-7599 x

Inspector: Melissa Kauffman

Start Date/Time: 11/7/2013 at 9:46:21 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION OF THE SPA

RECORD KEEPING DOES NOT MATCH READINGS.
FLOW METER IS NOT WORKING-PLEASE FIX OR REPLACE.

CLARITY IS GOOD
SIGNS ARE GOOD
DOORS ARE SECURE
SKIMMERS ARE CLEAN
EMERGENCY PHONE IN PLACE

DUE TO VERY LOW TO NO CHLORINE IN THE SPA;
SPA IS TO BE CLOSED UNTIL HEALTH DEPARTMENT REPOENS. OPENING SPA WITHOUT
AUTHORIZATION MAY RESULT IN A FINE AND FURTHER CLOSURES

Free Chlorine (1.5-5.0 ppm):	.1	Bromine (3.0-8.0 ppm):	Temperature(Max)	102
Combined Chlorine (0-.5 ppm):		Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):		Hardness (175-400 ppm):	pH (7.2-7.6):	7.3
Inlet Pressure:		Outlet Pressure:	Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

333-062-0135(1)

VIOLATION OF OAR 333-062-0135 (1) A flow meter is not provided, not properly installed, not located or is not functioning.

FLOW METER DOES NOT WORK OR PROPERLY GAGE FLOW RATES

Install and maintain a working flowmeter that measures the flow in gpm, mounted as recommended by the manufacturer, and that can be easily read by the operator.

PLEASE REPAIR OR REPLACE

Establishment: 2950003A

Page 13 of 17

Inspection Type: SEMI

Start Date/Time: 11/7/2013 at 9:46:21

333-062-0165(1.1)

VIOLATION OF OAR 333-062-0165 (1) The free available chlorine level is less than 1.5 ppm, specifically:

FREE CHLORINE IS AT .1 TO 0 PPM

CLOSE THE SPA POOL UNTIL A MINIMUM OF 1.5 ppm free available chlorine residual is achieved. Maintain the free available chlorine residual within the range set out in the spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 3.0 ppm,

USE TAYLOR TEST KIT EVERY MORNING BEFORE OPENING THE SPA. DO USE THE COMPUTER/AUTOMATIC FEEDER TO DOCUMENT CHEMICLE LEVELS.

Comments:

Site Report Generated: 6/23/2017 2:29:02 PM

Inspection By: Melissa Kauffman

Page 13

Establishment: 2950003A
Inspection Type: REINSP

Page 14 of 17
Start Date/Time: 6/25/2013 at 1:32:19

Historical 6/25/2013

SPA INSPECTION REPORT

Page 14 of 17

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
TILLAMOOK LODGING LIMITED PARTNERSHIP
ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER RD
TILLAMOOK, OR 97141

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2950003A Area: 62
Units: 0
County: 29

ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER
TILLAMOOK, OR 97141

Phone: (503) 842-7599 x
Inspector: Melissa Kauffman
Start Date/Time: 6/25/2013 at 1:32:19 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A REINSPECTION OF THE ASHLEY INN-SPA.

COMBINED CHLORINE
TOTAL CHLORINE
CYANURIC ACID
PH

WERE NOT CHECKED TODAY, SPA IS CLOSED DUE TO FILTER MAINTENANCE

CLAIRTY IS GOOD AND SPA POOL LIGHT IS IN PLACE AND SECURE.

Free Chlorine (1.5-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(Max
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		

Comments:

Site Report Generated: 6/23/2017 2:29:02 PM

Person In Charge

Inspection By: Melissa Kauffman

Page 14

Establishment: 2950003A
Inspection Type: REINSP

Page 15 of 17
Start Date/Time: 5/23/2013 at 1:51:29

Historical 5/23/2013

SPA INSPECTION REPORT

Page 15 of 17

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
TILLAMOOK LODGING LIMITED PARTNERSHIP
ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER RD
TILLAMOOK, OR 97141

Inspection Type: REINSP
Inspection Result: CLOSE
Establishment #: 2950003A Area: 62
Units: 0
County: 29

ASHLEY INN OF TILLAMOOK - SPA
1722 MAKINSTER
TILLAMOOK, OR 97141

Phone: (503) 842-7599 x
Inspector: Annette Pampush

Start Date/Time: 5/23/2013 at 1:51:29 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

pool light is loose, repair prior to opening.

pool to remain closed until chemistry and light are repaired

*DOOR TO OUTSIDE OF POOL HAS BEEN REPAIRED AND IS NOW SELF CLOSING

Free Chlorine (1.5-5.0 ppm):	.4	Bromine (3.0-8.0 ppm):	Temperature(Max	
Combined Chlorine (0-.5 ppm):	.6	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	
Total Alkalinity (80-200 ppm):		Hardness (175-400 ppm):	pH (7.2-7.6):	7.0
Inlet Pressure:		Outlet Pressure:	Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

Comments:

Site Report Generated: 6/23/2017 2:29:02 PM

Person In Charge

Inspection By: Annette Pampush

Page 15

Historical 4/30/2013

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

TILLAMOOK LODGING LIMITED PARTNERSHIP

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER RD

TILLAMOOK, OR 97141

Inspection Type: SEMI

Inspection Result: CLOSE

Establishment #: 2950003A Area: 62

Units: 0

County: 29

ASHLEY INN OF TILLAMOOK - SPA

1722 MAKINSTER

TILLAMOOK, OR 97141

Phone: (503) 842-7599 x

Inspector: Melissa Kauffman

Start Date/Time: 4/30/2013 at 10:17:12 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION

PROPER SAFETY EQUIPMENT

GOOD MAIN DRAIN COVERS.

CHLORINE (TRICHLOR TABS) ARE MANUALLY ADDED TO THE SPA. *AUTOMATIC FEEDER IS REQUIRED*

Free Chlorine (1.5-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(Max
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		

333-062-0125(1)(2)

VIOLATION OF OAR 333-062-0125 (1) & (2) The automatic disinfection equipment is not provided or is not operating.

THE AUTOMATIC CHLORINE - SALT FEEDER DOES NOT SEEM TO BE WORKING.

Provide automatic disinfecting equipment which introduces a disinfectant residual in the spa pool water at all times as described in Water Quality Parameters, OAR 333-062-0165, and Table 1.

DO NOT ADD TRICHLOR IN ADDITION TO SALT

333-062-0165(1.3)

VIOLATION OF OAR 333-062-0165 (1) The combined chlorine (chloramine) is greater than 0.5 ppm (0.5 mg / kg). Specifically:

COMBINED CHLORINE IS VERY HIGH 1.0PPM

Maintain the combined chlorine (chloramine) residual within the range set out in spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 0 ppm, measured combined chlorine. Combined chlorine (chloramines) is irritating to swimmers and

COMBINED CHLORINE SHOULD BE AT 0PPM. AND NEVER TO EXCEED .5PPM

PLEASE TEST FOR COMBINED AT LEAST ONCE A DAY.

333-062-0165(1.9)

VIOLATION OF OAR 333-062-0165 (1) The total alkalinity level does not comply with required water quality parameters. Specifically:

TOTAL ALKALINITY IS VERY LOW.

50PPM

Maintain the total alkalinity level greater than 80 ppm and less than 175 ppm, the ideal range being 80-125 ppm. Most modern finishes are durable within this range as long as the calcium saturation is maintained and the water is balanced.

PLEASE ADJUST CHEMICLES.

333-062-0165(5)

VIOLATION OF OAR 333-062-0165 (5) Oxidation or breakpoint chlorination is required to remove the excessive combined chlorine (chloramines), specifically:

Oxidize or breakpoint chlorinate the spa pool water when the combined chlorine level exceeds 0.5 ppm. Maintaining the combined chlorine or chloramine level as low as possible is most desirable.

PLEASE SEE GUIDELINES ON BREAK POINT CHLORINATION.

THE SPA IS TO BE CLOSED UNTIL PIC CAN DEMONSTRATE PROPER CHEMICLE BALANCE AND COMBINED CHLORINE IS LESS THAN .5PPM.

DO NOT OPEN THE SPA WITHOUT AUTHORIZATION FROM THE HEALTH DEPARTMENT 503-842-3909 (MELISSA KAUFFMAN)

Site Report Generated: 6/23/2017 2:29:02 PM

Person In Charge

Inspection By: Melissa Kauffman