

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name: MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL
50500 S HWY 101
NESKOWIN, OR 97149

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2940008B Area: 60
Units: 0
County: 29

NESKOWIN CREEK RV RESORT - POOL
50500 S HWY 101
NESKOWIN, OR 97149

Phone: (503) 392-3355 x
Inspector: Jaime Craig

Start Date/Time: 2/8/2017 at 10:34:25 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

ALKALINITY LOW AND HARDNESS IS QUITE HIGH.
BOTTOM OF POOL SHOWS SIGN OF CORROSION
OPERATOR SAYS THEY PLAN ON DRAINING POOL AND RESURFACING AT END OF SUMMER. THEY ALSO HAVE PLANS TO REPLACE DOORS/WINDOWS
HANDRAILS TIGHT
SIGNS ARE IN PLACE
RESTROOMS ARE OKAY- THERE IS RAW WOOD AROUND THE EDGES THAT SHOULD BE SEALED
LIFE HOOK AND TUBE AVAILABLE
DECK SURFACE HAS SOME CRACKS- SHOULD BE REPAIRED WHEN POOL IS RESURFACED

POOL TRAINING FLYER PROVIDED

Free Chlorine (0.8-5.0 ppm): 6.4 Bromine (3.0-8.0 ppm): Temperature(F): 88
Combined Chlorine (0-.5 ppm): 0.2 Cyanuric Acid (0-150 ppm): Clarity (Y/N): Y
Total Alkalinity (80-200 ppm): 40 Hardness (175-400 ppm): 520 pH (7.2-7.6): 7.6
Inlet Pressure: Outlet Pressure: Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-060-0200(1.09)

VIOLATION OF OAR 333-060-0200 (1) The total alkalinity is less than 80 ppm or greater than 200 ppm. Specifically:

ALKALINITY IS LOW

Maintain the total alkalinity within the range set out in the pool Water Quality Parameters, OAR 333-060-0200 and Table 3, ideal being approximately 80 - 125 ppm total alkalinity. Most modern pool finishes are durable within this range as long as the cal

RAISE

333-060-0200(1.11)

VIOLATION OF OAR 333-060-0200 (1) The calcium hardness is less than 175 ppm.

LEVEL AT 520

The recommended minimum level of calcium hardness is 175 ppm, per OAR 333-60-200 and Table 3. Most pools need about 250 - 300 ppm of calcium hardness. Low calcium hardness can create corrosive conditions in the pool

Add calcium chloride to increase t

REDUCE

Establishment: 2940008B

Page 2 of 17

Inspection Type: SEMI

Start Date/Time: 2/8/2017 at 10:34:25

Comments:

---

Site Report Generated: 6/23/2017 9:56:42 AM

---

Person In Charge

Inspection By: Jaime Craig

Page 2

**Historical 9/19/2016**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2940008B Area: 60

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-3355 x

Inspector: Jaime Craig

Start Date/Time: 9/19/2016 at 2:43:27 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

**POOL OPERATOR KNOWLEDGABLY OF POOL CHEMISTRY**

ALL LIFE SAVING EQUIPMENT AVAILABLE

FIRST AID KIT LACKS GLOVES

LOG OF DAILY CHEMISTRY AVAILABLE

DOORS SELF CLOSING

EQUIPMENT ROOM CLEAN AND WELL ORGANIZED

Free Chlorine (0.8-5.0 ppm):	<b>5.6</b>	Bromine (3.0-8.0 ppm):	Temperature(F):	<b>84</b>
Combined Chlorine (0-.5 ppm):	<b>.6</b>	Cyanuric Acid (0-150 ppm):	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>60</b>	Hardness (175-400 ppm):	pH (7.2-7.6):	<b>7.0</b>
Inlet Pressure:		Outlet Pressure:	<b>80</b>	Flow Rate:

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-060-0210(3)(d)

VIOLATION OF OAR 333-060-0210 (3)(d) The general-use swimming pool does not have a first aid kit or the kit has not been maintained.

**NO BLOODPORNE PATHOGEN KIT  
ONLY ONE PAIR OF GLOVES AVAILABLE  
TRASH BAG LACKING**

Provide a first aid kit, containing as a minimum, the supplies in Appendix A of the Public Swimming Pool rules. The kit must be stored in a protected location close to the pool and accessible for use. It must be kept properly stocked and not allowed to

Establishment: 2940008B

Page 4 of 17

Inspection Type: SEMI

Start Date/Time: 9/19/2016 at 2:43:27

Comments:

---

Site Report Generated: 6/23/2017 9:56:42 AM

---

Person In Charge

Inspection By: Jaime Craig

Page 4

**Historical 3/28/2016**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2940008B Area: 60

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-3355 x

Inspector: Mason Lyman

Start Date/Time: 3/28/2016 at 12:08:01 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SEMIANNUAL INSPECTION OF POOL-

LIGHTS OK

GATES/DOORS OK

STAIRS' 'LADDERS OK

WINDOWS OK

SAFETY EQUIPMENT OK

SIGNS OK

EMERGENCY PHONE WORKS

GOOD TURNOVER- UNDER 8 HOURS.

Free Chlorine (0.8-5.0 ppm):	<b>8.0</b>	Bromine (3.0-8.0 ppm):		Temperature(F):	<b>84</b>
Combined Chlorine (0-.5 ppm):	<b>0.2</b>	Cyanuric Acid (0-150 ppm):	<b>0</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>70</b>	Hardness (175-400 ppm):	<b>600</b>	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>75</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Establishment: 2940008B

Page 6 of 17

Inspection Type: SEMI

Start Date/Time: 3/28/2016 at 12:08:01

NO VIOLATIONS- THANKS.

---

Site Report Generated: 6/23/2017 9:56:42 AM

---

Person In Charge

Inspection By: Mason Lyman

Page 6

**Historical 8/14/2015**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2940008B Area: 60

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-3355 x

Inspector: Mason Lyman

Start Date/Time: 8/14/2015 at 3:02:36 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SKIMMERS OK  
GATES/DOORS OK  
DECK SURFACES OK  
SIGNAGE GOOD  
GOOD RECORD KEEPING

Free Chlorine (0.8-5.0 ppm):	<b>3.4</b>	Bromine (3.0-8.0 ppm):		Temperature(F):	
Combined Chlorine (0-.5 ppm):	<b>0.2</b>	Cyanuric Acid (0-150 ppm):		Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>70</b>	Hardness (175-400 ppm):	<b>600</b>	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>60</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-060-0155(1)

VIOLATION OF OAR 333-060-0155 (1) A flow meter is not provided, not properly installed, not located or is not functioning.

**HAVE A 2 INCH FLOW METER INSTALLED ON 2.5 INCH PIPE**

Install and maintain a flow meter in the recirculation piping, measuring flow in gallons per minute. Mount the flow meter per manufacturer's recommendation in a location where it can be easily read, and on a length of straight pipe.

**PLEASE CORRECT.**

Comments:

Site Report Generated: 6/23/2017 9:56:42 AM

**Historical 1/20/2015**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2940008B Area: 60

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-3355 x

Inspector: Mason Lyman

Start Date/Time: 1/20/2015 at 2:37:16 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

Comments:

Free Chlorine (0.8-5.0 ppm):	<b>5.4</b>	Bromine (3.0-8.0 ppm):	Temperature(F):	<b>82</b>	
Combined Chlorine (0-.5 ppm):	<b>0.0</b>	Cyanuric Acid (0-150 ppm):	Clarity (Y/N):	<b>Y</b>	
Total Alkalinity (80-200 ppm):	<b>80</b>	Hardness (175-400 ppm):	<b>400</b>	pH (7.2-7.6):	<b>7.8</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>70</b>

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

CORRECTIONS FROM LAST TIME: EAST DOOR NOW CLOSES FULLY AND WINDOWS NOW OPEN ONLY A FEW INCHES WHICH DOES NOT ALLOW CHILDREN FROM ILLEGALLY ENTERING FACILITY. GOOD JOB. TURNOVER RATE AT 7.6 HOURS- GOOD

\*\*CONSIDER REDUCING HARDNESS LEVEL TO 200-300 TO REDUCE SCALING POWER OF WATER.

TALKED TO PERSON IN CHARGE ABOUT REDUCING PH IN POOL FROM 7.8 IN THEIR RECENT RECORDS, DOWN LOWER TO REDUCE SCALING POWER OF WATER AND TO INCREASE EFFICIENCY OF DISINFECTANT USED (CAL HYPO).

SATURATION INDEX READING AT 0.4.

POOL SIZE, AROUND 32,000 GALLONS.

Site Report Generated: 6/23/2017 9:56:42 AM

Person In Charge

Inspection By: Mason Lyman



**Historical 7/31/2014**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2940008B Area: 60

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-3355 x

Inspector: Mason Lyman

Start Date/Time: 7/31/2014 at 12:21:12 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

**SEMI ANNUAL INSPECTION.**

**DECK EQUIPMENT IN GOOD REPAIR.**

**LADDERS AND STAIRS HAVE SECURE HAND RAILS.**

**WATER IS CLEAR AND HAS CLEAR DEPTH MARKERS.**

**SURFACE SKIMMERS ARE CLEAR.**

**SAFETY DEVICES (HOOK, BUOY, ROPE, ETC) ARE PROVIDED.**

Free Chlorine (0.8-5.0 ppm):	<b>8.</b>	Bromine (3.0-8.0 ppm):	Temperature(F):	<b>86</b>	
Combined Chlorine (0-.5 ppm):	<b>1.</b>	Cyanuric Acid (0-150 ppm):	Clarity (Y/N):	<b>Y</b>	
Total Alkalinity (80-200 ppm):	<b>70</b>	Hardness (175-400 ppm):	<b>600</b>	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:		
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-060-0105(2)(f.1)

VIOLATION OF OAR 333-060-0105 (2)(f) The gates or doors associated with the enclosure are not self-closing, not equipped with a functioning self-latching device at least 42 in. (1050 mm) above the exterior ground surface or are not able to be locked.

**EAST DOOR TO POOL NEEDS TO CLOSE PROPERLY.**

Construct, repair and maintain enclosure gates and doors with self-closing, self-latching, lockable devices. Latches must be at least 42 inches above the exterior ground surface. If the gate or door is not self-closing, self latching, or lockable; lock

**FIX DOOR SO THAT THE DOOR CLOSE FULLY TO ALLOW THE LOCKING MECHANISM TO WORK.**

Establishment: 2940008B

Page 10 of 17

Inspection Type: SEMI

Start Date/Time: 7/31/2014 at 12:21:12

333-060-0210(7)

VIOLATION OF OAR 333-060-0210 (7) There are doors, gates or windows that are not maintained so as to be lockable, or the pool is not properly secured when not in use.

**SOUTH WEST WINDOW OPENS TOO FAR TO ALLOW KIDS TO OBTAIN ACCESS TO POOL WHEN DOORS ARE CLOSED.**

Provide and maintain hardware on all doors, gates and windows so they operate properly and the pool can be secured when not in use. Secure the pool whenever the pool is not open for use.

**WINDOWS SHOULD NOT OPEN BY MORE THAN 4 INCHES TO KEEP BETTER SECURITY AROUND THE POOL AREA.**

EMERGENCY PHONE INSTALLED AND PROVIDED WITH ADDRESS FOR EMERGENCY PERSONNEL, A CORRECTION FROM LAST INSPECTION.

---

Site Report Generated: 6/23/2017 9:56:42 AM

---

Person In Charge

Inspection By: Mason Lyman

Page 10

**Historical 10/3/2013**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2940008B Area: 60

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-3355 x

Inspector: Melissa Kauffman

Start Date/Time: 10/3/2013 at 10:57:21 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.

OPENINGS ARE SECURE

DECK EQUIPMENT IN GOOD CONDITION

LADDERS ARE SECURE

WATER DEPTH LINES ARE CLEAR

SKIMMERS ARE CLEAN

SAFETY EQUIPMENT IS AVAILABLE

\*PLEASE INSTALL AN EMERGENCY PHONE WITH ADDRESS OF PARK IN THE POOL ROOM

POOL TEST KIT IS AVAILABLE

GOOD RECORD KEEPING

GOOD KNOWLEDGE OF POOL MAINTENANCE

Free Chlorine (0.8-5.0 ppm):	<b>5.4</b>	Bromine (3.0-8.0 ppm):		Temperature(F):	<b>83</b>
Combined Chlorine (0-.5 ppm):	<b>.2</b>	Cyanuric Acid (0-150 ppm):	<b>0</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>60</b>	Hardness (175-400 ppm):	<b>270</b>	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>70</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Establishment: 2940008B

Page 12 of 17

Inspection Type: SEMI

Start Date/Time: 10/3/2013 at 10:57:21

Comments:

---

Site Report Generated: 6/23/2017 9:56:42 AM

---

Person In Charge

Inspection By: Melissa Kauffman

Page 12

**Historical 4/30/2013**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2940008B Area: 60

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-3355 x

Inspector: Melissa Kauffman

Start Date/Time: 4/30/2013 at 12:56:34 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.

CLARITY IS GREAT

SIGNS ARE GREAT

ENCLOSURE IS SECURE/ SELF CLOSING DOOR

SIGNS ARE GREAT

SHOWERS ARE PROVIDED

RECORD KEEPING IS GOOD

CHEMISTRY IS GREAT

SKIMMERS ARE GOOD

WEIRS ARE IN PLACE

GREAT DEMONSTRATION OF KNOWLEDGE.

Free Chlorine (0.8-5.0 ppm):	<b>7.8</b>	Bromine (3.0-8.0 ppm):		Temperature(F):	<b>85</b>
Combined Chlorine (0-.5 ppm):	<b>.1</b>	Cyanuric Acid (0-150 ppm):	<b>0</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>50</b>	Hardness (175-400 ppm):	<b>300</b>	pH (7.2-7.6):	<b>7.8</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>8HRS</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Establishment: 2940008B

Page 14 of 17

Inspection Type: SEMI

Start Date/Time: 4/30/2013 at 12:56:34

ALKALINITY IS LESS THAN 80PPM

LOW ALKALINITY MAY CAUSE UNSTABLE PH AND AND CORROSION/ETCHING OF THE POOL/SPA WALL SURFACES.

---

Site Report Generated: 6/23/2017 9:56:42 AM

---

Person In Charge

Inspection By: Melissa Kauffman

Page 14

Establishment: 2940008B  
Inspection Type: REINSP

Page 15 of 17  
Start Date/Time: 9/7/2012 at 10:28:48

**Historical 9/7/2012**

**POOL PROGRAM INSPECTION REPORT**

Page 15 of 17

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MIKE MCLEOD  
NESKOWIN CREEK RV RESORT - POOL  
50500 S HWY 101  
NESKOWIN, OR 97149

Inspection Type: REINSP  
Inspection Result: COMPLD  
Establishment #: 2940008B Area: 60  
Units: 0  
County: 29

NESKOWIN CREEK RV RESORT - POOL  
50500 S HWY 101  
NESKOWIN, OR 97149

Phone: (503) 392-3355 x  
Inspector: Melissa Kauffman

Start Date/Time: 9/7/2012 at 10:28:48 AM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A REINSPECTION

THE CHLORINE LEVELS ARE AT 5.0PPM AND THE COMBINED CHLORINE IS AT .4PPM

Free Chlorine (0.8-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(F):
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (0-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		

THANK YOU FOR YOUR CORRECTIONS

---

Site Report Generated: 6/23/2017 9:56:42 AM

---

Person In Charge

Inspection By: Melissa Kauffman

Page 15

**Historical 9/4/2012**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2940008B Area: 60

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - POOL

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-3355 x

Inspector: Melissa Kauffman

Start Date/Time: 9/4/2012 at 11:56:36 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION

CLARITY IS GREAT

POOL SURFACE IS GREAT

SKIMMERS ARE IN GOOD CONDITION

GOOD SIGNS FOR SAFTEY

POOL SAFTEY EQUIPMENT IS PROVIDED

POOL/SPA IS UNDER 24 HR SURVEILLANCE

DOOR ARE SECURE

SHOWER ARE IN GOOD CONDITION

GOOD RECORD KEEPING

PIC HAS GOOD DEMONSTRATION OF KNOWLEDGE

Free Chlorine (0.8-5.0 ppm):	<b>3.6</b>	Bromine (3.0-8.0 ppm):	Temperature(F):		
Combined Chlorine (0-.5 ppm):	<b>.4</b>	Cyanuric Acid (0-150 ppm):	Clarity (Y/N):	<b>Y</b>	
Total Alkalinity (80-200 ppm):	<b>130</b>	Hardness (175-400 ppm):	<b>500</b>	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>0</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					



Establishment: 2940008B

Page 17 of 17

Inspection Type: SEMI

Start Date/Time: 9/4/2012 at 11:56:36

CALCIUM HARDNESS IS PRETTY HIGH 500PPM  
IT IS SUGGESTED TO NOT EXCEED 400PPM

---

Site Report Generated: 6/23/2017 9:56:42 AM

---

Person In Charge

Inspection By: Melissa Kauffman

Page 17