

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943

Owner Name:  
MIKE MCLEOD

NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Inspection Type: SEMI  
Inspection Result: COMPLD  
Establishment #: 2950037 Area: 62

Units: 0  
County: 29

NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Phone: (503) 392-4155 x  
Inspector: Jaime Craig

Start Date/Time: 2/8/2017 at 10:41:59 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE ALKALINITY IS ON LOW SIDE AT 70 PPM  
RECORDS KEPT WELL  
SIGNS AVAILABLE

Free Chlorine (1.5-5.0 ppm):	<b>80.</b>	Bromine (3.0-8.0 ppm):	Temperature(Max)	<b>102</b>	
Combined Chlorine (0-.5 ppm):	<b>0.</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):		
Total Alkalinity (80-200 ppm):	<b>70</b>	Hardness (175-400 ppm):	<b>480</b>	pH (7.2-7.6):	<b>7.2</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>40</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-062-0150(2)(f)

VIOLATION OF OAR 333-062-0150 (2)(f) The bathhouse walls, ceilings, floors and showers not maintained. Specifically:

**WOOD AROUND THE DIVIDER SHOULD HAVE A SEALER OR PAINT APPLIED**

Maintain walls and ceilings so they are smooth, easily cleanable and impervious to water. Provide shower stall floors which are nonslip and impervious to water.

Comments:

Site Report Generated: 6/23/2017 9:56:08 AM

Person In Charge

Inspection By: Jaime Craig

Establishment: 2950037  
Inspection Type: REINSP

Page 2 of 18  
Start Date/Time: 9/19/2016 at 2:42:53

**Historical 9/19/2016**

**SPA INSPECTION REPORT**

Page 2 of 18

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MIKE MCLEOD  
NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Inspection Type: REINSP  
Inspection Result: COMPLD  
Establishment #: 2950037 Area: 62  
Units: 0  
County: 29

NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Phone: (503) 392-4155 x  
Inspector: Jaime Craig

Start Date/Time: 9/19/2016 at 2:42:53 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

ATTEMPTED TO INSPECT, SPA CLOSED FOR MAINTENANCE ISSUES.

Free Chlorine (1.5-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(Max
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		

Comments:

---

Site Report Generated: 6/23/2017 9:56:08 AM

---

Person In Charge

Inspection By: Jaime Craig

Page 2

**Historical 3/28/2016**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MIKE MCLEOD  
NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Inspection Type: SEMI  
Inspection Result: COMPLD  
Establishment #: 2950037 Area: 62  
Units: 0  
County: 29

NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Phone: (503) 392-4155 x  
Inspector: Mason Lyman

Start Date/Time: 3/28/2016 at 12:12:26 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SAFETY EQUIPMENT OK

SIGNS OK

SKIMMERS OK

\*\*PLEASE TIGHTEN HANDRAIL INTO SPA.

GOOD RECORD KEEPING

REVIEWED WITH PIC ABOUT SHOCKING, AND RECORD KEEPING, TURNOVER AND ALGAECIDES.

Free Chlorine (1.5-5.0 ppm):	<b>3.6</b>	Bromine (3.0-8.0 ppm):		Temperature(Max	<b>102</b>
Combined Chlorine (0-.5 ppm):	<b>0.4</b>	Cyanuric Acid (30-150 ppm):	<b>0</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>80</b>	Hardness (175-400 ppm):	<b>240</b>	pH (7.2-7.6):	<b>7.6</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>55</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-062-0175(4)

VIOLATION OF OAR 333-062-0175 (4) The hydrotherapy (jet) pump timer switch is accessible to bathers from within the spa or the 15-minute maximum timer limit is exceeded, specifically:

**NEW TIMER INSTALLED. TIMED AT 30 MINUTES.**

Locate the hydrotherapy timer switch so bathers must exit spa to activate. Provide a timer which does not exceed the 15-minute maximum time cycle.

**PLEASE INSTALL 15 MINUTE TIMER.**

RECOMMEND INSTALLING THEIR AIR VENT EXHAUST ABOVE THE SPA TO PREVENT STAGNANT AIR, AND RESHOCKING SPA.

---

Site Report Generated: 6/23/2017 9:56:08 AM

Establishment: 2950037  
Inspection Type: REINSP

Page 4 of 18  
Start Date/Time: 8/20/2015 at 12:14:21

**Historical 8/20/2015**

**SPA INSPECTION REPORT**

Page 4 of 18

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MIKE MCLEOD  
NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Inspection Type: REINSP  
Inspection Result: COMPLD  
Establishment #: 2950037 Area: 62  
Units: 0  
County: 29

NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Phone: (503) 392-4155 x  
Inspector: Mason Lyman

Start Date/Time: 8/20/2015 at 12:14:21 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

REINSPECTION OF SPA FACILITY-

TALKED TO PIC ABOUT FLOW METER NEEDING REPLACEMENT. ALL CHEMISTRY IS WITHIN PARAMETERS, AND IS READY TO OPEN. FACILITY GOT NEW MURIATIC ACID, AND IS USING IT EFFECTIVELY.

READY TO REOPEN.

Free Chlorine (1.5-5.0 ppm):	<b>6.2</b>	Bromine (3.0-8.0 ppm):		Temperature(Max)	<b>101</b>
Combined Chlorine (0-.5 ppm):	<b>0.0</b>	Cyanuric Acid (30-150 ppm):	<b>40</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>80</b>	Hardness (175-400 ppm):	<b>290</b>	pH (7.2-7.6):	<b>7.6</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>0</b>

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

Comments:

Site Report Generated: 6/23/2017 9:56:08 AM

---

Person In Charge

Inspection By: Mason Lyman

Page 4

**Historical 8/14/2015**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: CONTIN

Establishment #: 2950037 Area: 62

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-4155 x

Inspector: Mason Lyman

Start Date/Time: 8/14/2015 at 3:04:26 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

FLOW RATE IS GREAT  
SKIMMERS OK  
GOOD DECK SURFACE  
GOOD RECORD KEEPING

Free Chlorine (1.5-5.0 ppm):	<b>3.2</b>	Bromine (3.0-8.0 ppm):	Temperature(Max	<b>102</b>	
Combined Chlorine (0-.5 ppm):	<b>1.0</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	<b>Y</b>	
Total Alkalinity (80-200 ppm):	<b>80</b>	Hardness (175-400 ppm):	<b>280</b>	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:	<b>50</b>	

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-062-0165(1.3)

VIOLATION OF OAR 333-062-0165 (1) The combined chlorine (chloramine) is greater than 0.5 ppm (0.5 mg / kg). Specifically:

**COMBINED CHLORINE AT 1.0 PPM.**

Maintain the combined chlorine (chloramine) residual within the range set out in spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 0 ppm, measured combined chlorine. Combined chlorine (chloramines) is irritating to swimmers and

**ARE SUPERCHLORINATING NOW. POOL IS CLOSED UNTIL COMBINED IS MAINTAINED BELOW 0.5 PPM.**

333-062-0255(1)

VIOLATION OF OAR 333-062-0255(1) The spa pool meets one or more of the closure criteria. The spa pool license holder, operator, or responsible supervisor is responsible for closing the pool.

**COMBINED AT 1.0 PPM. SPA IS CLOSED UNTIL CONTACT OFFICE AT 5003-842-3909.**

The spa pool has been closed by the appropriate pool staff, while they eliminate the reason for the spa pool closure in accordance with OAR 333-062-0255(3). When the reason for the closure is eliminated, the spa pool may reopen. THE POOL STAFF HAS ACTED

Establishment: 2950037

Page 6 of 18

Inspection Type: SEMI

Start Date/Time: 8/14/2015 at 3:04:26

Comments:

---

Site Report Generated: 6/23/2017 9:56:08 AM

---

Person In Charge

Inspection By: Mason Lyman

Page 6

**Historical 1/30/2015**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2950037 Area: 62

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-4155 x

Inspector: Mason Lyman

Start Date/Time: 1/30/2015 at 1:41:59 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

Comments:

Free Chlorine (1.5-5.0 ppm):	<b>5.0</b>	Bromine (3.0-8.0 ppm):	Temperature(Max)	<b>101</b>
Combined Chlorine (0-.5 ppm):	<b>.4</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>90</b>	Hardness (175-400 ppm):	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:	<b>0</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

SPA WAS JUST FINISHING SUPERCHLORINATION STEP.  
\*\*TALKED TO PIC ABOUT POOL CHEMISTRY AND ABOUT UPCOMING POOL CLASS.

FACILITY IS READY TO OPEN.

SKIMMERS/ DECK SURFACE OK  
LADDERS/ STAIRS OK  
SIGNS/ SAFETY EQUIPMENT OK  
GATES/ DOORS OK  
GOOD RECORD KEEPING

Site Report Generated: 6/23/2017 9:56:08 AM

Establishment: 2950037  
Inspection Type: REINSP

Page 8 of 18  
Start Date/Time: 1/20/2015 at 2:49:06

**Historical 1/20/2015**

**SPA INSPECTION REPORT**

Page 8 of 18

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MIKE MCLEOD  
NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Inspection Type: REINSP  
Inspection Result: CONTIN  
Establishment #: 2950037 Area: 62  
Units: 0  
County: 29

NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Phone: (503) 392-4155 x  
Inspector: Mason Lyman

Start Date/Time: 1/20/2015 at 2:49:06 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

LADDERS OK  
STAIRS/HANDRAILS OK  
DOORS/GATES/WINDOWS OK  
SKIMMERS CLEAN AND CLEAR  
PHONE OPERATIONAL  
SIGNS AND POOL RULES UP  
DECK SURFACE IN COMPLIANCE

Free Chlorine (1.5-5.0 ppm):	<b>3.4</b>	Bromine (3.0-8.0 ppm):	Temperature(Max)	<b>103</b>
Combined Chlorine (0-.5 ppm):	<b>1.2</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>130</b>	Hardness (175-400 ppm):	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:	<b>50</b>

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-062-0165(1.11)

VIOLATION OF OAR 333-062-0165 (1) The calcium hardness is less than 100 ppm, specifically:

**WATER HARDNESS AT 50 PPM.**

The recommended minimum level of calcium hardness is 200 ppm, per OAR 333-062-0165 and Table 1. Low calcium hardness can cause aggressive corrosion, particularly in the heater. The pool should be maintained with the calcium demand fully saturated, but n

**PIC CORRECTED AND ADDED HARDNESS INCREASE TO MAINTAINED WATER LEVEL AT >150 PPM TO COMPLY WITH HEALTH RULES.**

333-062-0165(1.3)

VIOLATION OF OAR 333-062-0165 (1) The combined chlorine (chloramine) is greater than 0.5 ppm (0.5 mg / kg). Specifically:

**COMBINED CHLORINE AT 1.2 PPM.**

Maintain the combined chlorine (chloramine) residual within the range set out in spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 0 ppm, measured combined chlorine. Combined chlorine (chloramines) is irritating to swimmers and

**PIC SUPERCHLORINATED SPA DURING INSPECTION. SPA CLOSED UNTIL COMBINED CHLORINE AND HARDNESS ARE WITHIN PARAMETERS.**



333-062-0255(1)

VIOLATION OF OAR 333-062-0255(1) The spa pool meets one or more of the closure criteria. The spa pool license holder, operator, or responsible supervisor is responsible for closing the pool.

**SPA HAS BEEN CLOSED DURING SUPERCHLORINATION PROCESS TO REDUCE COMBINED CHLORINE BELOW 0.5 PPM, AND DID EXTRA STEP TO INCREASE HARDNESS LEVEL FROM 50 TO 150 PPM.**

The spa pool has been closed by the appropriate pool staff, while they eliminate the reason for the spa pool closure in accordance with OAR 333-062-0255(3). When the reason for the closure is eliminated, the spa pool may reopen. THE POOL STAFF HAS ACTED

**AFTER CHEMICAL TESTING IS DONE AND COMPLIES WITH OREGON SPA RULES, SPA CAN REOPEN TO PUBLIC.**

SEMIANNUAL INSPECTION OF SPA-

30 MINUTE TURNOVER ACHIEVED IN SPA- GOOD

SATURATION INDEX OF SPA- -0.4 (SLIGHTLY CORROSIVE), INCREASE HARDNESS FROM 50 TO >150 PPM TO ACHIEVE BETTER WATER BALANCE.

Site Report Generated: 6/23/2017 9:56:08 AM

---

Person In Charge

Inspection By: Mason Lyman

Page 9

**Historical 8/2/2014**

**SPA INSPECTION REPORT**

Page 10 of 18

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: REINSP

Inspection Result: COMPLD

Establishment #: 2950037 Area: 62

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-4155 x

Inspector: Annette Pampush

Start Date/Time: 8/2/2014 at 08:42:39

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

facility emailed that all violations have been corrected. spa was emptied completely and chemistry is now spot on. a recheck /consult inspection will occur

Free Chlorine (1.5-5.0 ppm):

Bromine (3.0-8.0 ppm):

Temperature(Max

Combined Chlorine (0-.5 ppm):

Cyanuric Acid (30-150 ppm):

Clarity (Y/N):

Total Alkalinity (80-200 ppm):

Hardness (175-400 ppm):

pH (7.2-7.6):

Inlet Pressure:

Outlet Pressure:

Flow Rate:

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

Comments:

---

Site Report Generated: 6/23/2017 9:56:08 AM

Inspection By: Annette Pampush

Page 10

**Historical 7/31/2014**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: CLOSE

Establishment #: 2950037 Area: 62

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-4155 x

Inspector: Mason Lyman

Start Date/Time: 7/31/2014 at 12:21:27 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

CLARITY IS GOOD.

**\*\*CLOSING SPA BECAUSE OF VALUES OUT OF RANGE.**

Free Chlorine (1.5-5.0 ppm):	<b>11.</b>	Bromine (3.0-8.0 ppm):	Temperature(Max)	<b>102</b>
Combined Chlorine (0-.5 ppm):	<b>2.</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):		Hardness (175-400 ppm):	pH (7.2-7.6):	<b>7.0</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:	<b>60</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

Comments:

Site Report Generated: 6/23/2017 9:56:08 AM

Person In Charge

Inspection By: Mason Lyman

**Historical 10/3/2013**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2950037 Area: 62

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-4155 x

Inspector: Melissa Kauffman

Start Date/Time: 10/3/2013 at 11:00:44 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION OF THE SPA

CLAIRTY IS GOOD

LADDER IS SECURE

ENTRANCE TO POOL AREA IS SECURE

DECK SURFACE IS IN GOOD REPAIR

SPA BASIN IS IN GOOD CONDITION

SHOWER ROOMS ARE CLEAN

GOOD SIGNS FOR PATRON SHOWERS

TEST KIT AVAILABLE

Free Chlorine (1.5-5.0 ppm):	<b>7.2</b>	Bromine (3.0-8.0 ppm):		Temperature(Max)	<b>98</b>
Combined Chlorine (0-.5 ppm):	<b>0.</b>	Cyanuric Acid (30-150 ppm):	<b>0</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>60</b>	Hardness (175-400 ppm):	<b>270</b>	pH (7.2-7.6):	<b>.7</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>70</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Establishment: 2950037

Page 13 of 18

Inspection Type: SEMI

Start Date/Time: 10/3/2013 at 11:00:44

Comments:

---

Site Report Generated: 6/23/2017 9:56:09 AM

---

Person In Charge

Inspection By: Melissa Kauffman

Page 13

**Historical 4/30/2013**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2950037 Area: 62

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-4155 x

Inspector: Melissa Kauffman

Start Date/Time: 4/30/2013 at 1:02:35 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.

GREAT RECORD KEEPING

POOL ROOM WELL ORGANIZED

TURN OVER RATE IS GREAT

GREAT MAIN DRAIN SHUT OFF

SAFETY EQUIPMENT IN PLACE

CHEMISTRY IS GOOD

GREAT DEMONSTRATION OF KNOWLEDGE

VGB COVERS ARE GOOD

Free Chlorine (1.5-5.0 ppm):	<b>7.2</b>	Bromine (3.0-8.0 ppm):		Temperature(Max)	<b>103</b>
Combined Chlorine (0-.5 ppm):	<b>2.</b>	Cyanuric Acid (30-150 ppm):	<b>0</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>60</b>	Hardness (175-400 ppm):	<b>300</b>	pH (7.2-7.6):	<b>7.2</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>20MI</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Establishment: 2950037

Page 15 of 18

Inspection Type: SEMI

Start Date/Time: 4/30/2013 at 1:02:35

ALKALINITY IS SLIGHTLY LOW

---

Site Report Generated: 6/23/2017 9:56:09 AM

---

Person In Charge

Inspection By: Melissa Kauffman

Page 15

Establishment: 2950037  
Inspection Type: REINSP

Page 16 of 18  
Start Date/Time: 9/7/2012 at 10:31:52

**Historical 9/7/2012**

**SPA INSPECTION REPORT**

Page 16 of 18

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MIKE MCLEOD  
NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Inspection Type: REINSP  
Inspection Result: COMPLD  
Establishment #: 2950037 Area: 62  
Units: 0  
County: 29

NESKOWIN CREEK RV RESORT - SPA  
50500 S HWY 101  
NESKOWIN, OR 97149

Phone: (503) 392-4155 x  
Inspector: Melissa Kauffman

Start Date/Time: 9/7/2012 at 10:31:52 AM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A REINSPECTION

CHLORINE IS 5.2PPM AND COMBINED IS .4PPM

Free Chlorine (1.5-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(Max
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		

THANK YOU FOR YOUR CORRECTIONS

Site Report Generated: 6/23/2017 9:56:09 AM

---

Inspection By: Melissa Kauffman

Page 16



**Historical 9/4/2012**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:

MIKE MCLEOD

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Inspection Type: SEMI

Inspection Result: CLOSE

Establishment #: 2950037 Area: 62

Units: 0

County: 29

NESKOWIN CREEK RV RESORT - SPA

50500 S HWY 101

NESKOWIN, OR 97149

Phone: (503) 392-4155 x

Inspector: Melissa Kauffman

Start Date/Time: 9/4/2012 at 11:58:54 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.

CLARITY IS GREAT

POOL SURFACE IS GREAT

SKIMMERS ARE GOOD

LADDERS ARE SECURE

SPA UNDER 24.HR SURVAILENCE

GATES/DOORS ARE SECURE

GOOD SIGNS FOR SAFTEY

SAFTEY EQUIPMENT IS PROVIDED

Free Chlorine (1.5-5.0 ppm):	<b>7.2</b>	Bromine (3.0-8.0 ppm):	Temperature(Max
Combined Chlorine (0-.5 ppm):	<b>1.6</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):		Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:		Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):			<b>0</b>

333-062-0165(1.2)

VIOLATION OF OAR 333-062-0165 (1) The free available chlorine is greater than 5 ppm, specifically:

**THE FREE CHLORINE LEVELS ARE 7.2 AND NOT TO EXCEED 5.0PPM**

Maintain the free available chlorine residual within the range set out in Spa Water Quality Parameters, OAR 333-062-0165, and Table 1. The ideal being 3.0 ppm, measured free available chlorine.

**PLEASE CORRECT CHEMISTRY**

333-062-0165(1.3)

VIOLATION OF OAR 333-062-0165 (1) The combined chlorine (chloramine) is greater than 0.5 ppm (0.5 mg / kg). Specifically:

**COMBINED CHLORINE IS 1.6PPM AND IS NOT TO EXCEED .05PPM**

Maintain the combined chlorine (chloramine) residual within the range set out in spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 0 ppm, measured combined chlorine. Combined chlorine (chloramines) is irritating to swimmers and

**PLEASE CORRECT CHEMISTRY BEFORE REOPENING THE POOL**

Establishment: 2950037

Page 18 of 18

Inspection Type: SEMI

Start Date/Time: 9/4/2012 at 11:58:54

SPA SHALL REMAIN CLOSED UNTIL CHEMISTRY IS IN COMPLIANCE

---

Site Report Generated: 6/23/2017 9:56:09 AM

---

Inspection By: Melissa Kauffman

Page 18