

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:
SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: CLOSE
Establishment #: 2950027 Area: 62
Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Annette Pampush

Start Date/Time: 1/25/2017 at 1:43:14 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE SPA SURFACE IS VERY PITTED, THIS MAY BE DUE TO CHEMISTRY LEVELS BEING TO CORROSIVE.

SPA IS CLOSED UNTIL COMBINED CHLORINE CAN BE REDUCED TO UNDER .5PPM

Free Chlorine (1.5-5.0 ppm):	4.8	Bromine (3.0-8.0 ppm):	Temperature(Max)	103
Combined Chlorine (0-.5 ppm):	0.8	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	50	Hardness (175-400 ppm):	pH (7.2-7.6):	7.2
Inlet Pressure:		Outlet Pressure:	Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):	768			

333-062-0135(1)

VIOLATION OF OAR 333-062-0135 (1) A flow meter is not provided, not properly installed, not located or is not functioning.

FLOW METER DOES NOT APPEAR TO BE WORKING

Install and maintain a working flowmeter that measures the flow in gpm, mounted as recommended by the manufacturer, and that can be easily read by the operator.

Comments:

Site Report Generated: 6/23/2017 2:30:52 PM

Person In Charge

Inspection By: Annette Pampush

Establishment: 2950027

Inspection Type: REINSP

Start Date/Time: 4/1/2016 at 10:20:25

Historical 4/1/2016

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Mason Lyman

Start Date/Time: 4/1/2016 at 10:20:25 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

REINSPECTION OF SPA-

FREE CHLORINE AT 5.0 PPM,
COMBINED CHLORINE AT 0.4 PPM.
PH AT 7.2

READY TO OPEN. KEEP COMBINED BELOW 0,5 PPM.

Free Chlorine (1.5-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(Max
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		

Comments:

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Mason Lyman

Historical 3/29/2016

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: CONTIN
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Mason Lyman

Start Date/Time: 3/29/2016 at 3:39:41 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SKIMMERS OK
DECK SURFACE OK
SAFETY EQUIPMENT OK
EMERGENCY PHONE AVAILABLE IN POOL ENCLOSURE
GOOD CLARITY TO THE WATER
FACILITY RECENTLY SWITCHED FROM STABILIZED CHLORINE, TO CAL-HYPO.

Free Chlorine (1.5-5.0 ppm):	10.0	Bromine (3.0-8.0 ppm):		Temperature(Max)	103
Combined Chlorine (0-.5 ppm):	1.0	Cyanuric Acid (30-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	90	Hardness (175-400 ppm):	150	pH (7.2-7.6):	8.0
Inlet Pressure:		Outlet Pressure:		Flow Rate:	60

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-062-0255(3)(a.1)

VIOLATION OF OAR 333-062-0255 (3)(a) The combined chlorine levels exceed 0.5 ppm.

SPA COMBINED CHLORINE AT 1.0 PPM.

Combined chlorine should be kept as low as possible. The spa should not have a pool smell or cause eye or mucus membrane irritation (trichloramine / nitrogen trichloride), The only way to reduce the irritating nitrogen trichloride at an indoor spa, is t

GET TO BELOW 0.5, IDEALLY TO 0.0 PPM THRU SHOCKING. GET PH TO BETWEEN 7.2-7.6. WHEN READY, REOPEN, CALL OFFICE AT 503-842-3909 SO A REINSPECTION CAN OCCUR.

Establishment: 2950027

Page 4 of 19

Inspection Type: SEMI

Start Date/Time: 3/29/2016 at 3:39:41

****STRONGLY RECOMMEND A SCALE TO ACCURATELY DETERMINE THE AMOUNTS OF CHEMICALS YOU ARE ADDING TO THE POOL/SPA. PLEASE RECORD AMOUNTS IN RECORD SHEETS.**

****TALKED TO STAFF MEMBERS AND FIXED THE WAY THEY WERE MEASURING COMBINED CHLORINE. PLEASE USE 5 DROPS FOR EVERY TEST IN THE FUTURE.**

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Mason Lyman

Page 4

Historical 7/29/2015

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Mason Lyman

Start Date/Time: 7/29/2015 at 11:29:49 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

Comments:

Free Chlorine (1.5-5.0 ppm):	13.2	Bromine (3.0-8.0 ppm):	Temperature(Max)	102
Combined Chlorine (0-.5 ppm):	0.	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):		Hardness (175-400 ppm):	pH (7.2-7.6):	7.2
Inlet Pressure:		Outlet Pressure:	Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

Establishment: 2950027

Page 6 of 19

Inspection Type: REINSP

Start Date/Time: 7/29/2015 at 11:29:49

REINSPECTION OF SPA FACILITY-

RECHECK OF NON-COMPLAINE CHEMISTRY-

FC AT 13.2 PPM

CC AT 0 (GREAT JOB)

PH AT 7.2

TEMPERATURE AT 101.8F.

**RECOMMEND SWITCHING FROM COLORIMETER TEST TO TITRATION TEST FOR MEASURING FREE CHLORINE.

**REPAIR FLOW METER TO ALLOW TO WORK, TO TURNOVER RATE CAN BE CALCULATED.

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Mason Lyman

Page 6

Historical 7/27/2015

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: CONTIN
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Mason Lyman

Start Date/Time: 7/27/2015 at 11:24:11 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

INSPECTION OF SPA

50 GPM- UNDER 20 MINUTE TURNOVER

**INCLUDE IN RECORDS HOW MUCH OF EACH CHEMICAL YOU PUT INTO SPA WHEN MAKING ADDITIONS.

**RECOMMEND SWITCHING FROM COLORIMETRIC TEST TO TITRATION TEST FOR CHECKING CHLORINE. MUCH MORE ACCURATE, NO NEED FOR DILLUTION.

**RECOMMEND USING A SCALE TO ACCURATELY WEIGH CHEMICALS BEFORE PUTTING IN POOL FOR GREATER ACCURACY AS WELL.

**CHECK PAPERWORK OF MAIN DRAIN FITTING. SEE WHEN THE VGB MAIN DRAIN EXPIRES, AS MANY LAST 4-5 YEARS AND IT IS THAT LONG SINCE YOU MAY HAVE INSTALLED IT.

Free Chlorine (1.5-5.0 ppm):	6.0	Bromine (3.0-8.0 ppm):	Temperature(Max)	101
Combined Chlorine (0-.5 ppm):	.5	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	120	Hardness (175-400 ppm):	pH (7.2-7.6):	8.0
Inlet Pressure:		Outlet Pressure:	Flow Rate:	50
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

333-062-0165(1.7)

VIOLATION OF OAR 333-062-0165 (1) The pH is less than 7.2 or greater than 7.6. specifically:

PH OF SPA IS AT 8.0

Maintain the pH levels within the range set out in the spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 7.2 - 7.6.

PLEASE REDUCE TO 7.2-7.6. WILL REINSPECT LATER THIS WEEK TO CHECK COMPLIANCE.

Establishment: 2950027

Page 8 of 19

Inspection Type: SEMI

Start Date/Time: 7/27/2015 at 11:24:11

Comments:

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Mason Lyman

Page 8

Establishment: 2950027

Inspection Type: REINSP

Start Date/Time: 2/3/2015 at 12:17:29

Historical 2/3/2015

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: REINSP
Inspection Result: COMPLD
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Mason Lyman

Start Date/Time: 2/3/2015 at 12:17:29 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

Comments:

Free Chlorine (1.5-5.0 ppm):	14.0	Bromine (3.0-8.0 ppm):		Temperature(Max)	101
Combined Chlorine (0-.5 ppm):	0.2	Cyanuric Acid (30-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	100	Hardness (175-400 ppm):	150	pH (7.2-7.6):	7.2
Inlet Pressure:		Outlet Pressure:		Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Establishment: 2950027
Inspection Type: REINSP

Page 10 of 19
Start Date/Time: 2/3/2015 at 12:17:29

POOL EQUIPMENT OK

ADJUSTED ALKALINITY AND HARDNESS AND WITHIN PROPER RANGES. KEEP AN EYE ON ALKALINITY AND READJUST IT ACCORDINGLY, THEN GET HARDNESS WITHIN RANGE.

FREE CHLORINE HAS CLIMBED UP TO 14 PPM, PLEASE REDUCE TO AVOID STAINING AND OTHER ISSUES.

KEEP TAKING POOL AND SPA CHEMISTRY AS OFTEN AS NECESSARY ACCORDING TO OREGON STATE RULES.

SPA OPEN AGAIN FOR SERVICE.

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Mason Lyman

Page 10

Historical 2/2/2015

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: CONTIN
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Mason Lyman

Start Date/Time: 2/2/2015 at 1:20:34 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SKIMMERS OK
LADDERS/ STIARS OK
GATES / DOORS OK
SAFETY EQUIPMENT OK
SIGNS/ RECORDS OK
TURNOVER IS LESS THAN 30 MINUTES- GOOD

**KEEP RECORDS FOR AT LEAST 2 YEARS.

Free Chlorine (1.5-5.0 ppm):	8.8	Bromine (3.0-8.0 ppm):	Temperature(Max)	104
Combined Chlorine (0-.5 ppm):	0.	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	30	Hardness (175-400 ppm):	pH (7.2-7.6):	7.2
Inlet Pressure:		Outlet Pressure:	Flow Rate:	60
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

333-062-0165(1.11)

VIOLATION OF OAR 333-062-0165 (1) The calcium hardness is less than 100 ppm, specifically:

HARDNESS AT 50 PPM.

The recommended minimum level of calcium hardness is 200 ppm, per OAR 333-062-0165 and Table 1. Low calcium hardness can cause aggressive corrosion, particularly in the heater. The pool should be maintained with the calcium demand fully saturated, but n

PLEASE CORRECT TO COMPLY.

333-062-0165(1.9)

VIOLATION OF OAR 333-062-0165 (1) The total alkalinity level does not comply with required water quality parameters. Specifically:

ALKALINITY AT 30 PPM.

Maintain the total alkalinity level greater than 80 ppm and less than 175 ppm, the ideal range being 80-125 ppm. Most modern finishes are durable within this range as long as the calcium saturation is maintained and the water is balanced.

PLEASE INCREASE TO COMPLY WITH HEALTH RULES.

333-062-0165(3)

VIOLATION OF OAR 333-062-0165 (3) The spa pool water quality parameters are not being tested at the required frequencies or are not recorded, specifically:

ALKALINITY IS ONLY BEING TESTED EVERY WEEK.

Complete and record the required spa pool water tests at the minimum frequencies as described in OAR 333-62-165(3)(a) through (i).

PLEASE INCREASE TO ONCE A DAY TO KEEP TRACK OF ALKALINITY READINGS.

333-062-0255(1)

VIOLATION OF OAR 333-062-0255(1) The spa pool meets one or more of the closure criteria. The spa pool license holder, operator, or responsible supervisor is responsible for closing the pool.

CLOSURE OF SPA BASED UPON LOW ALKALINITY AND HARDNESS. OPERATOR PLACED SIGN ON SPA TO ANNOUNCE CLOSURE UNTIL COMPLIANCE.

The spa pool has been closed by the appropriate pool staff, while they eliminate the reason for the spa pool closure in accordance with OAR 333-062-0255(3). When the reason for the closure is eliminated, the spa pool may reopen. THE POOL STAFF HAS ACTED

PLEASE CORRECT, AND CALL OFFICE ONCE PARAMETERS ARE CORRECT FOR 2 HOURS. WILL RECHECK.

Comments:

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Mason Lyman

Historical 8/19/2014

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Mason Lyman

Start Date/Time: 8/19/2014 at 9:26:57 AM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

****SPA TEMPERATURE WAS 105F WHEN FIRST CAME IN, COOLED TO 104F. SHOULD NOT BE ABOVE 104F.**

****TRI-CHLOR IN THE DISINFECTANT USED FOR BOTH THE SPA AND POOL EVEN THOUGH THEY ARE INDOOR POOLS.**

SKIMMERS OK
LADDERS OK

Free Chlorine (1.5-5.0 ppm):	.1	Bromine (3.0-8.0 ppm):	Temperature(Max)	104
Combined Chlorine (0-.5 ppm):	.6	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	90	Hardness (175-400 ppm):	pH (7.2-7.6):	7.6
Inlet Pressure:		Outlet Pressure:	Flow Rate:	12
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

333-062-0065(2)

VIOLATION OF OAR 333-062-0065 (2) The spa pool lighting and area lighting is not sufficient and underwater lighting is not used.

UNDERWATER LIGHT AT SPA HAS ELECTRICAL POWER TURNED OFF TO LIGHT, BUT LIGHT IS LOOSE.

Provide lighting at a minimum of 2 watts incandescent, or equivalent, per sq.ft. of deck surface, for night and indoor spa use..

PLEASE REPAIR/REPLACE LIGHT.

Establishment: 2950027

Page 14 of 19

Inspection Type: SEMI

Start Date/Time: 8/19/2014 at 9:26:57

Comments:

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Mason Lyman

Page 14

Establishment: 2950027

Inspection Type: SEMI

Start Date/Time: 10/1/2013 at 2:14:16

Historical 10/1/2013

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Melissa Kauffman

Start Date/Time: 10/1/2013 at 2:14:16 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION

CLARITY IS GOOD
POOL TEMP 103F
FREE CHLORINE 4.8
COMBINED .2
PH 7.8*
TOTAL ALKALINITY 90
CALCIUM HARDNESS 230
CYA 0 -STAFF DRAINS WATER TO CONTROL CYA
-PH IS BEING LOWERED AT THIS TIME

800 GAL SPA
PHONE IN POOL AREA
SAFETY EQUIPMENT PROVIDED
DOORS ARE SECURE
GOOD RECORD KEEPING
GOOD DEMONSTRATION OF KNOWLEDGE
FLOW METER 60GPM

Free Chlorine (1.5-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(Max
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		

Establishment: 2950027

Page 16 of 19

Inspection Type: SEMI

Start Date/Time: 10/1/2013 at 2:14:16

PLEASE BUDGET TO REPAIR SPA BASIN.

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Melissa Kauffman

Page 16

Historical 5/2/2013

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Melissa Kauffman

Start Date/Time: 5/2/2013 at 1:42:21 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.
SPA SURFACE APPEARS TO HAVE HIGH LEVELS OF CORROSION.

CLARITY IS GOOD

FREE CHLORINE IS VERY HIGH, IT IS SUGGESTED TO KEEP FREE CHLORINE BETWEEN 2.0PPM AND 4.0PPM

TURNOVER FOR A 800GAL SPA IS ABOUT EVERY 20 MINUTES.

SAFETY EQUIPMENT IS PROVIDED

RECORD KEEPING NEEDS TO INCLUDE COMBINED CHLORINE AND CYANURIC ACID.

WHEN CHEMISTRY IS NOT IN PROPER PARAMETERS CLOSE THE SPA.

Free Chlorine (1.5-5.0 ppm):	7.8	Bromine (3.0-8.0 ppm):		Temperature(Max)	96
Combined Chlorine (0-.5 ppm):	.4	Cyanuric Acid (30-150 ppm):	0	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	50	Hardness (175-400 ppm):	50	pH (7.2-7.6):	8.0
Inlet Pressure:		Outlet Pressure:		Flow Rate:	0

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-062-0060(1)

VIOLATION OF OAR 333-062-0060 (1) The spa pool wall /floor finish is not impervious or enduring, smooth or easily cleanable. Specifically:

THE SPA SURFACE APPEARS TO HIGH HIGH LEVELS OF CORROSION

Wall and floor finishes shall be of non-toxic materials which are impervious and enduring. Finishes shall be smooth and easily cleanable.

PLEASE CONSIDER A DIFFERENT CHLORINE BRAND. AND INCREASING TOTAL ALKALINITY.

333-062-0165(1.11)

VIOLATION OF OAR 333-062-0165 (1) The calcium hardness is less than 100 ppm, specifically:

CALCIUM HARDNESS IS 50PPM

The recommended minimum level of calcium hardness is 200 ppm, per OAR 333-062-0165 and Table 1. Low calcium hardness can cause aggressive corrosion, particularly in the heater. The pool should be maintained with the calcium demand fully saturated, but n

SPA WILL BECOME CORROSIVE WITH LOW CALCIUM CONTENT.

PLEASE ADJUST CHEMISTRY

333-062-0165(1.9)

VIOLATION OF OAR 333-062-0165 (1) The total alkalinity level does not comply with required water quality parameters. Specifically:

TOTAL ALKALINITY IS LOW 50PPM

Maintain the total alkalinity level greater than 80 ppm and less than 175 ppm, the ideal range being 80-125 ppm. Most modern finishes are durable within this range as long as the calcium saturation is maintained and the water is balanced.

**LOW ALKALINITY MAY RESULT IN WATER WITH A GREEN TINT OR
CORROSION.ETCHING OF THE SPA WALLS. PH WILL ALSO FLUCTUATE.**

**THE SPA SHALL BE CLOSED UNTIL PH, TOTAL ALKALINITY AND CALCIUM HARDNESS ARE BALANCED.
CONTACT MELISSA AT (503-842-3909) BEFORE OPENING.**

Site Report Generated: 6/23/2017 2:30:53 PM

Person In Charge

Inspection By: Melissa Kauffman

Page 18

Historical 9/11/2012

SPA INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

SHILO INN TILLAMOOK, LLC
SHILO INN TILLAMOOK - SPA
2515 MAIN AVE N
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2950027 Area: 62

Units: 0
County: 29

SHILO INN TILLAMOOK - SPA
11600 SW SHILO LN
PORTLAND, OR 97225

Phone: (503) 842-7971 x
Inspector: Melissa Kauffman

Start Date/Time: 9/11/2012 at 12:55:41 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

- CLARITY IS GOOD
- LADDERS ARE SECURE
- GOOD SIGNS
- EMERGENCY PHONE AVAILABLE
- SKIMMERS ARE GOOD
- GOOD RECORD KEEPING

Free Chlorine (1.5-5.0 ppm):	1.8	Bromine (3.0-8.0 ppm):	Temperature(Max)	96
Combined Chlorine (0-.5 ppm):	.2	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	Y
Total Alkalinity (80-200 ppm):	80	Hardness (175-400 ppm):	pH (7.2-7.6):	7.1
Inlet Pressure:		Outlet Pressure:	Flow Rate:	0
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

333-062-0060(1)

VIOLATION OF OAR 333-062-0060 (1) The spa pool wall /floor finish is not impervious or enduring, smooth or easily cleanable. Specifically:

THE SPA SURFACE IS ROUGH, WORN AND NOT SMOOTH

Wall and floor finishes shall be of non-toxic materials which are impervious and enduring. Finishes shall be smooth and easily cleanable.

PLEASE REPAIR SPA SURFACE SO THAT IT IS SMOOTH AND CLEAN.

Comments:

Site Report Generated: 6/23/2017 2:30:53 PM