

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:

COVE CORPORATION INC

MIAMI COVE RV PARK

503 E GARIBALDI AVE

GARIBALDI, OR 97118

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2920185 Area: 31

Units: 14

County: 29

MIAMI COVE RV PARK

PO BOX 545

GARIBALDI, OR 97118

Phone: (503) 322-2295 x

Inspector: Jaime Craig

Start Date/Time: 1/30/2017 at 2:01:16 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

PERSON IN CHARGE EASILY FOUND
PARK CLEAN AND WELL MAINTAINED.
BATHROOMS CLEAN/STOCKED
LAUNDRY ROOM CLEAN- IN GOOD REPAIR-VENTILATED
BACK FLOW PREVENTION DEVICES ON MOST FACETS (MISSING ON A COUPLE OR NEED TO BE PUT ON SPLITTERS)
MOST SEWER SLOPED CORRECTLY (CORRECT SITE 2)
EACH SITE IDENTIFIED WITH NUMBER
GARBAGE SERVICE REGULARLY AND AREA PROTECTED.
TALKED WITH PIC ABOUT SITE SPACING MIN OF 10F.
THANKS!

Comments:

Site Report Generated: 6/23/2017 9:16:32 AM

Person In Charge

Inspection By: Jaime Craig

Establishment: 2920185

Page 2 of 11

Inspection Type: SEMI

Start Date/Time: 9/16/2016 at 11:39:15

Historical 9/16/2016

RECREATIONAL PARK INSPECTION REPORT

Page 2 of 11

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

COVE CORPORATION INC

MIAMI COVE RV PARK

503 E GARIBALDI AVE

GARIBALDI, OR 97118

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2920185 Area: 31

Units: 14

County: 29

MIAMI COVE RV PARK

PO BOX 545

GARIBALDI, OR 97118

Phone: (503) 322-2295 x

Inspector: Jaime Craig

Start Date/Time: 9/16/2016 at 11:39:15 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

PERSON IN CHARGE EASILY FOUND
PARK CLEAN AND WELL MAINTAINED.
BATHROOMS CLEAN/STOCKED
LAUNDRY ROOM CLEAN- IN GOOD REPAIR-VENTILATED
**SHIELD LIGHTS ON CEILING
BACK FLOW PREVENTION DEVICES ON MOST FAUCETS
MOST SEWER SLOPED CORRECTLY
EACH SITE IDENTIFIED WITH NUMBER
GARBAGE SERVICE REGULARLY AND AREA PROTECTED.
TALKED WITH PIC ABOUT SITE SPACING MIN OF 10F.
THANKS!

Comments:

Site Report Generated: 6/23/2017 9:16:33 AM

Person In Charge

Inspection By: Jaime Craig

Page 2

Establishment: 2920185

Page 3 of 11

Inspection Type: SEMI

Start Date/Time: 1/25/2016 at 12:53:24

Historical 1/25/2016 RECREATIONAL PARK INSPECTION REPORT

Page 3 of 11

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
COVE CORPORATION INC
MIAMI COVE RV PARK
503 E GARIBALDI AVE
GARIBALDI, OR 97118

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920185 Area: 31
Units: 14
County: 29

MIAMI COVE RV PARK
PO BOX 545
GARIBALDI, OR 97118

Phone: (503) 322-2295 x
Inspector: Mason Lyman

Start Date/Time: 1/25/2016 at 12:53:24 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

INSPECTION OF RV PARK-

SITES WELL SPACED
GOOD FLOW OF TRAFFIC AROUND PARK
OUTSIDE OF BUILDINGS WELL MAINTAINED
SEWER LINES MOSTLY SLOPED CORRECTLY
BACKFLOW PREVENTION DEVICES ON FAUCETS
GARBAGE COLLECTION AREA PROTECTED
NO EVIDENCE OF RODENTS/PESTS IN FACILITY
PERSON IN CHARGE EASILY FOUND ON SITE

**PERSON IN CHARGE SAID SHE WILL BE GETTING REPLACEMENT WHITE ID NUMBERS AT SITES TO MAKE IT EASILY FOR EMERGENCY PERSONNEL TO DETERMINE SITES FROM EACH OTHER.

Site Report Generated: 6/23/2017 9:16:33 AM

Person In Charge

Inspection By: Mason Lyman

Page 3

Historical 7/2/2015 RECREATIONAL PARK INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
COVE CORPORATION INC
MIAMI COVE RV PARK
503 E GARIBALDI AVE
GARIBALDI, OR 97118

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920185 Area: 31
Units: 14
County: 29

MIAMI COVE RV PARK
PO BOX 545
GARIBALDI, OR 97118

Phone: (503) 322-2295 x
Inspector: Mason Lyman

Start Date/Time: 7/2/2015 at 11:42:21 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

BACKFLOW PREVENTERS ON MOST FAUCETS
SEWER LINES DRAINING PROPERLY
GOOD FLOW OF TRAFFIC AROUND PARK/ NO BLOCKAGES
GOOD SOLID WASTE MANAGEMENT
RESTROOMS CLEAN AND IN GOOD REPAIR.
PIC EASILY FOUND AND ON SITE
FLOORS/WALLS/CEILING CLEANABLE AND SMOOTH
**PLEASE CLEAN OFF VENT IN MENS RESTROOM IN ALLOW PROPER AIR CIRCULATION.

333-031-0062(1)

Violation of OAR 333-031-0062 (1) The camping spaces are not identified.

SEVEERAL CAMPING SITES (9-10) ARE NOT IDENTIFIABLE FROM THE STREET.

Identify each camping space by letter, number, or name.

PLEASE CORRECT.

333-031-0062(2.1)

Violation of 333-031-0062 (2) The camping space is inadequately sized to provide the needed separation distances between camping vehicles and tents.

2 SITES (9-10) ARE WITHIN 6 FEET OF EACH OTHER.

Provide at least ten feet of space separating camping vehicles, tents, awnings, or carports from camping vehicles or tents in other spaces.

PLEASE CORRECT.

Establishment: 2920185

Page 5 of 11

Inspection Type: SEMI

Start Date/Time: 7/2/2015 at 11:42:21

Comments:

Site Report Generated: 6/23/2017 9:16:33 AM

Person In Charge

Inspection By: Mason Lyman

Page 5

Establishment: 2920185

Page 6 of 11

Inspection Type: SEMI

Start Date/Time: 1/12/2015 at 1:53:25

Historical 1/12/2015 RECREATIONAL PARK INSPECTION REPORT

Page 6 of 11

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
COVE CORPORATION INC
MIAMI COVE RV PARK
503 E GARIBALDI AVE
GARIBALDI, OR 97118

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920185 Area: 31
Units: 14
County: 29

MIAMI COVE RV PARK
PO BOX 545
GARIBALDI, OR 97118

Phone: (503) 322-2295 x
Inspector: Mason Lyman

Start Date/Time: 1/12/2015 at 1:53:25 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

SEMIANNUAL INSPECITON OF PARK

GOOD SPACING BETWEEN SITES
RESTROOMS CLEAN AND WELL MAINTAINED
GOOD VENTILATION IN LAUNDRY ROOMS
SPACES ARE MARKED FOR EMERGENCY PERSONNEL
MOST SITES HAVE BACKFLOW PREVENTERS
SEWER LINES PROPERLY SLOPED TO ALLOW DRAINAGE
OUTSIDE OF BUILDINGS IN GOOD REPAIR
GOOD TRAFFIC FLOW AROUND STIES
PIC FOUND ON SITES

**TALKED TO PIC ABOUT CLEANING VENT COVERS IN RESTROOMS TO ALLOW BETTER AIR MOVEMENT
**TALKED TO PIC ABOUT STANDING WATER AND HARBORAGE FOR FLIES
**TALKED TO PIC ABOUT CLEANING UP DEBRIS ON SOME SITES TO DISCOURAGE HARBORAGE OF PESTS AT PARK IN THE FUTURE.

Establishment: 2920185

Page 7 of 11

Inspection Type: SEMI

Start Date/Time: 1/12/2015 at 1:53:25

Comments:

Site Report Generated: 6/23/2017 9:16:33 AM

Person In Charge

Inspection By: Mason Lyman

Page 7

Establishment: 2920185

Page 8 of 11

Inspection Type: SEMI

Start Date/Time: 7/24/2014 at 3:21:37

Historical 7/24/2014

RECREATIONAL PARK INSPECTION REPORT

Page 8 of 11

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

COVE CORPORATION INC

MIAMI COVE RV PARK

503 E GARIBALDI AVE

GARIBALDI, OR 97118

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2920185 Area: 31

Units: 14

County: 29

MIAMI COVE RV PARK

PO BOX 545

GARIBALDI, OR 97118

Phone: (503) 322-2295 x

Inspector: Mason Lyman

Start Date/Time: 7/24/2014 at 3:21:37 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THIS IS THE SEMI ANNUAL INSPECTION.

SPOTS ARE EVENLY SPACED.

BACK FLOW PREVENTERS ARE INSTALLED AND IN WORKING CONDITION.

SEWER LINES ARE SLOPED CORRECTLY.

LAUNDRY AND RESTROOM LOOK GOOD.

OUTER BUILDINGS ARE IN GOOD SHAPE.

GARBAGE COLLECTION AREA IS SET APART AND IN GOOD CONDITION WITH MINIMAL CHANCE OF CONTAMINATION.

WELL SPACED PARK WITH NO VEHICLES BLOCKING TRAFFIC OR FLOW OF VEHICLES AROUND PARK.

NO VIOLATIONS AT THIS TIME, THANKS.

Site Report Generated: 6/23/2017 9:16:33 AM

Person In Charge

Inspection By: Mason Lyman

Page 8

Establishment: 2920185

Page 9 of 11

Inspection Type: SEMI

Start Date/Time: 7/30/2013 at 8:25:32

Historical 7/30/2013 RECREATIONAL PARK INSPECTION REPORT

Page 9 of 11

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
COVE CORPORATION INC
MIAMI COVE RV PARK
503 E GARIBALDI AVE
GARIBALDI, OR 97118

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920185 Area: 31
Units: 14
County: 29

MIAMI COVE RV PARK
PO BOX 545
GARIBALDI, OR 97118

Phone: (503) 322-2295 x
Inspector: Melissa Kauffman

Start Date/Time: 7/30/2013 at 8:25:32 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.

CAMP SITES ARE EASILY IDENTIFIABLE
RVS ARE SPACED 10FT APART
LONG TERM CAMPERS HAVE MINIMAL DEBRIS BUILD UP
SEWAGE LINES ARE SLOPED
SPIGOTS THAT WERE AVAILABLE HAD BACK FLOW PREVENTORS
RESTROOMS ARE IN GOOD CONDITION WITH RUNNING WATER, FREE OF MOLD, FLOOR/WALLS IN GOOD CONDITION
CAMP GROUNDS ARE PROPERLY MAINTAINED

THERE ARE NO VIOLATIONS AT THIS TIME, THANK YOU.

Comments:

Site Report Generated: 6/23/2017 9:16:33 AM

Person In Charge

Inspection By: Melissa Kauffman

Page 9

Historical 1/3/2013 RECREATIONAL PARK INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
COVE CORPORATION INC
MIAMI COVE RV PARK
503 E GARIBALDI AVE
GARIBALDI, OR 97118

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920185 Area: 31

Units: 14
County: 29

MIAMI COVE RV PARK
PO BOX 545
GARIBALDI, OR 97118

Phone: (503) 322-2295 x
Inspector: Melissa Kauffman

Start Date/Time: 1/3/2013 at 10:51:55 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.

THERE ARE 11 ACTIVE SITES
ALL ANTI SIPOHON DEVICES ARE WEATHERIZED AND WRAPPED
GARBAGE IS PROPERLY STORED
OVERALL APPEARANCE OF GROUNDS IS GOOD
PICNIC TABLES ARE IN GOOD REPAIR
ALL SITES ARE EASILY IDENTIFIABLE
PIC WAS NOT ONSITE AT THIS TIME
BUILDING EXTERIOR IS IN GOOD CONDITION
RESTROOMS WERE LOCKED AT THIS TIME

333-031-0062(2.1)

Violation of 333-031-0062 (2) The camping space is inadequately sized to provide the needed separation distances between camping vehicles and tents.

THERE ARE SEVERAL CAMPERS WITH ITEMS, VEHICLES OR TENTS WITH LESS THAN 10' OF DISTANCE APART

Provide at least ten feet of space separating camping vehicles, tents, awnings, or carports from camping vehicles or tents in other spaces.

PLEASE CORRECT

Comments:

Site Report Generated: 6/23/2017 9:16:33 AM

Establishment: 2920185

Page 11 of 11

Inspection Type: SEMI

Start Date/Time: 9/24/2012 at 3:08:43

Historical 9/24/2012 RECREATIONAL PARK INSPECTION REPORT

Page 11 of 11

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141

(503) 842-3943

Owner Name:

COVE CORPORATION INC

MIAMI COVE RV PARK

503 E GARIBALDI AVE

GARIBALDI, OR 97118

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2920185 Area: 31

Units: 14

County: 29

MIAMI COVE RV PARK

PO BOX 545

GARIBALDI, OR 97118

Phone: (503) 322-2295 x

Inspector: Melissa Kauffman

Start Date/Time: 9/24/2012 at 3:08:43 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION

RESTROOM IS IN GOOD REPAIR

LAUNDRY ROOM IS IN GOOD REPAIR

ALL SITES ARE CLEARLY MARKED

SEWAGE LINES ARE PROPERLY SLOPED

ALL BACKFLOW DEVICES THAT WERE VISIBLE ARE INSTALLED.

CAMP GROUNDS ARE IN GOOD CONDITION, THANK YOU

Comments:

Site Report Generated: 6/23/2017 9:16:33 AM

Person In Charge

Inspection By: Melissa Kauffman

Page 11