

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: REINSP  
Inspection Result: COMPLD  
Establishment #: 2950036A Area: 62  
Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Mason Lyman

Start Date/Time: 4/4/2016 at 2:55:15 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

REINSPECTION OF SPA-

FACILITY FIXED JET TIMER TO ONLY BE 15 MINUTES, DOWN FROM 30 MINUTES. GREAT JOB. FREE CHLORINE IS NOW AT 0.8 PPM, NEARLY TO 1.5 PPM. CONTINUE CHECKING CHEMISTRY EVERY 2 HOURS FOR SPA TO KEEP FREE CHLORINE ABOVE 1.5, AND COMBINED CHLORINE BELOW 0.5 PPM.

Free Chlorine (1.5-5.0 ppm):	<b>0.5</b>	Bromine (3.0-8.0 ppm):	Temperature(Max	<b>101</b>
Combined Chlorine (0-.5 ppm):	<b>0.0</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>80</b>	Hardness (175-400 ppm):	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:	<b>0</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

READY TO REOPEN, AS CHEMICALS HAVE BEEN DOSED.

---

Site Report Generated: 6/19/2017 4:50:29 PM

Person In Charge

Inspection By: Mason Lyman

**Historical 3/28/2016**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: SEMI  
Inspection Result: CONTIN  
Establishment #: 2950036A Area: 62

Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Mason Lyman

Start Date/Time: 3/28/2016 at 2:55:30 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

GATES OK  
STAIRS/LADDERS OK  
SAFETY EQUIPMENT OK  
DEPTH MARKINGS OK

Free Chlorine (1.5-5.0 ppm):	<b>9.0</b>	Bromine (3.0-8.0 ppm):		Temperature(Max)	<b>102</b>
Combined Chlorine (0-.5 ppm):	<b>1.8</b>	Cyanuric Acid (30-150 ppm):	<b>200</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>200</b>	Hardness (175-400 ppm):	<b>300</b>	pH (7.2-7.6):	<b>7.2</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>90</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-062-0135(1)

VIOLATION OF OAR 333-062-0135 (1) A flow meter is not provided, not properly installed, not located or is not functioning.

**FLOW METER FOR EAST SIDE OF SPA APPEARS TO BE BROKEN.**

Install and maintain a working flowmeter that measures the flow in gpm, mounted as recommended by the manufacturer, and that can be easily read by the operator.

**PLEASE REPAIR/REPLACE.**

333-062-0175(4)

VIOLATION OF OAR 333-062-0175 (4) The hydrotherapy (jet) pump timer switch is accessible to bathers from within the spa or the 15-minute maximum timer limit is exceeded, specifically:

**TIMER GOES FOR 30 MINUTES.**

Locate the hydrotherapy timer switch so bathers must exit spa to activate. Provide a timer which does not exceed the 15-minute maximum time cycle.

**PLEASE REPLACE, OR ONLY ALLOW TO GO FOR UP TO 15 MINUTES.**

VIOLATION OF OAR 333-062-0255 (3)(a) The combined chlorine levels exceed 0.5 ppm.

**COMBINED CHLORINE AT 1.8 PPM.  
SPA CLOSED.**

Combined chlorine should be kept as low as possible. The spa should not have a pool smell or cause eye or mucus membrane irritation (trichloramine / nitrogen trichloride), The only way to reduce the irritating nitrogen trichloride at an indoor spa, is t

**FACILITY WAS INCORRECTLY READING COMBINED CHLORINE LEVELS, TALKED TO STAFF ABOUT HOW TO READ LEVELS. SPA CLOSED. PLEASE GET BELOW 0.5PPM BEFORE REOPENING. PLEASE CALL OFFICE AT 503-842-3909 WHEN READY TO REOPEN.**

\*\*SKIMMERS ARE VERY DIRTY. PLEASE CLEAN OUT MORE FREQUENTLY.

\*\*RECOMMEND TO GET A SCALE TO PROPERLY MEASURE CHEMICALS PUTTING IN THE POOL/SPA.

---

Site Report Generated: 6/19/2017 4:50:29 PM

---

Person In Charge

Inspection By: Mason Lyman

Page 3

Establishment: 2950036A  
Inspection Type: REINSP

Page 4 of 14  
Start Date/Time: 9/29/2015 at 2:00:58

**Historical 9/29/2015**

**SPA INSPECTION REPORT**

Page 4 of 14

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: REINSP  
Inspection Result: COMPLD  
Establishment #: 2950036A Area: 62

Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Mason Lyman

Start Date/Time: 9/29/2015 at 2:00:58 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

REINSPECTION OF FACILITY-

CHEMISTRY- ALL CHEMISTRY IS UNDER CONTROL. PIC DUMPED THE WATER THERE. TOOK CYA DOWN FROM 400+ TO 60 PPM.

SPA IS REOPEN AT THIS TIME.

Free Chlorine (1.5-5.0 ppm):	<b>8.4</b>	Bromine (3.0-8.0 ppm):		Temperature(Max	<b>103</b>
Combined Chlorine (0-.5 ppm):	<b>0.</b>	Cyanuric Acid (30-150 ppm):	<b>60</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>100</b>	Hardness (175-400 ppm):	<b>280</b>	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>0</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Comments:

---

Site Report Generated: 6/19/2017 4:50:29 PM

---

Person In Charge

Inspection By: Mason Lyman

Page 4

**Historical 9/22/2015**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: SEMI  
Inspection Result: CONTIN  
Establishment #: 2950036A Area: 62  
Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Mason Lyman

Start Date/Time: 9/22/2015 at 3:55:07 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SKIMMERS OK  
GATES/DOORS OK  
STAIRS/LADDERS OK  
PHONE SIGN UP

GOOD RECORD KEEPING SHEETS- INCLUDE QUANTITY OF CHEMICALS ADDED ON SHEET.

Free Chlorine (1.5-5.0 ppm):	<b>1.0</b>	Bromine (3.0-8.0 ppm):		Temperature(Max)	<b>103</b>
Combined Chlorine (0-.5 ppm):	<b>1.2</b>	Cyanuric Acid (30-150 ppm):	<b>500</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>110</b>	Hardness (175-400 ppm):	<b>270</b>	pH (7.2-7.6):	<b>7.2</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>73</b>

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-062-0165(3)

VIOLATION OF OAR 333-062-0165 (3) The spa pool water quality parameters are not being tested at the required frequencies or are not recorded, specifically:

**NOT CHECKING COMBINED CHLORINE.**

Complete and record the required spa pool water tests at the minimum frequencies as described in OAR 333-62-165(3)(a) through (i).

**TAUGHT PIC ABOUT HOW TO TEST FOR CC. PLEASE CHECK WHENEVER YOU CHECK FOR FREE CHLORINE.**

333-062-0255(3)(a.1)

VIOLATION OF OAR 333-062-0255 (3)(a) The combined chlorine levels exceed 0.5 ppm.

**COMBINED CHLORINE AT 1.2 PPM.**

Combined chlorine should be kept as low as possible. The spa should not have a pool smell or cause eye or mucus membrane irritation (trichloramine / nitrogen trichloride), The only way to reduce the irritating nitrogen trichloride at an indoor spa, is t

**SPA CLOSED. SHOCK SPA AND GET COMBINED TO BELOW 0.5 PPM.**

Establishment: 2950036A

Page 6 of 14

Inspection Type: SEMI

Start Date/Time: 9/22/2015 at 3:55:07

\*\*GET TO KNOW HOW MANY GALLONS IS THE POOL AND SPA.

\*\*RECOMMEND TO OBTAIN A SCALE TO ACCURATELY MEASURE AMOUNTS OF CHEMICALS TO POOL/SPA.

\*\*CALL OFFICE AT 503-842-3909 WHEN CHEMISTRY TO READY TO GO.

---

Site Report Generated: 6/19/2017 4:50:29 PM

---

Person In Charge

Inspection By: Mason Lyman

Page 6

Establishment: 2950036A  
Inspection Type: REINSP

Page 7 of 14  
Start Date/Time: 3/27/2015 at 2:04:02

**Historical 3/27/2015**

**SPA INSPECTION REPORT**

Page 7 of 14

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: REINSP  
Inspection Result: COMPLD  
Establishment #: 2950036A Area: 62  
Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Mason Lyman

Start Date/Time: 3/27/2015 at 2:04:02 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

Comments:

Free Chlorine (1.5-5.0 ppm):	<b>2.6</b>	Bromine (3.0-8.0 ppm):		Temperature(Max)	<b>99</b>
Combined Chlorine (0-.5 ppm):	<b>0.4</b>	Cyanuric Acid (30-150 ppm):	<b>0</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>110</b>	Hardness (175-400 ppm):	<b>270</b>	pH (7.2-7.6):	<b>7.4</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>90</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

REINSPECTION OF SPA TODAY-

SPA NOW OPEN AND READY FOR PATRONS.  
SPA HAD EXTRA CHLORINE PUT IN LAST NIGHT, READING HAVE STABILIZED AND READY TO GO.

ADDED BAKING SODA TO INCREASE ALKALINITY.

---

Site Report Generated: 6/19/2017 4:50:29 PM

---

Person In Charge

Inspection By: Mason Lyman

Page 7

**Historical 3/26/2015**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: SEMI  
Inspection Result: CONTIN  
Establishment #: 2950036A Area: 62  
Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Mason Lyman

Start Date/Time: 3/26/2015 at 3:34:39 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

INSPECTION OF SPA-

VOLUME- 2,000 GALLONS  
EMERGENCY PHONE SIGN AVAILABLE  
GATE OK  
ENCLOSURE AND FENCING OK  
GOOD RECORD KEEPING

\*\*TALKED TO PIC ABOUT BACKWASHING FILTERS LESS OFTEN, ONLY AFTER FILTERS INCREASE FURTHER IN PRESSURE, BUT STILL ALLOWING PROPER FLOW AND TURNOVER.  
\*\*INCREASE RECORD KEEPING TO DOING FREE AND COMBINED CHLORINE EVERY 2 HOURS, AND PH EVERY 2 HOURS, TALKED TO MAINTENANCE MAN ABOUT RECOMMENDATIONS.

PLEASE CALL OFFICE AFTER PROPER CHEMISTRY HAS BEEN REACHED, AND THEN OK TO REOPEN POOL. WILL REINSPECT AT NEXT AVAILABLE TIME, AND WILL RECHECK CHEMISTRY.

Free Chlorine (1.5-5.0 ppm):	<b>0.2</b>	Bromine (3.0-8.0 ppm):	Temperature(Max	<b>103</b>
Combined Chlorine (0-.5 ppm):	<b>0.6</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>80</b>	Hardness (175-400 ppm):	pH (7.2-7.6):	<b>7.6</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:	<b>90</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

333-062-0165(1.3)

VIOLATION OF OAR 333-062-0165 (1) The combined chlorine (chloramine) is greater than 0.5 ppm (0.5 mg / kg). Specifically:

**CC AT 0.6 PPM.**

Maintain the combined chlorine (chloramine) residual within the range set out in spa Water Quality Parameters, OAR 333-062-0165, and Table 1, the ideal being 0 ppm, measured combined chlorine. Combined chlorine (chloramines) is irritating to swimmers and

**PLEASE CORRECT/ SUPERCHLORINATE.**



Establishment: 2950036A

Page 9 of 14

Inspection Type: SEMI

Start Date/Time: 3/26/2015 at 3:34:39

333-062-0255(3)(a)

VIOLATION OF OAR 333-062-0255 (3)(a) The disinfectant level does not meet the parameters in OAR 333-062-0170 (1 ), or items (a) thru (c) of Table 1.

**DISINFECTANT LEVEL AT 0.2 PPM, ALSO COMBINED CHLORINE IS AT 0.6 PPM.**

The minimum residual for free chlorine is 1.5 ppm and the maximum is 5 ppm for spas. Consistent maintenance of an ORP of 750 mv. or higher, while maintaining the free chlorine with in the correct ppm range, can allow the operator to reduce the manual tes

**RECOMMEND TO CLOSE SPA UNTIL ABOVE 1.5 PPM FREE CHLORINE, AND BELOW 0.5 PPM COMBINED CHLORINE.**

Comments:

---

Site Report Generated: 6/19/2017 4:50:30 PM

---

Person In Charge

Inspection By: Mason Lyman

Page 9

**Historical 8/20/2014**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: SEMI  
Inspection Result: COMPLD  
Establishment #: 2950036A Area: 62

Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Mason Lyman

Start Date/Time: 8/20/2014 at 12:50:25 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SKIMMERS OK  
15 PSI OUTPUT  
GATES/DOORS OK

\*\*SPA WITH LOTS OF FOAM  
\*\*SPA WITH LOTS OF COMBINED CHLORINE, RECOMMEND SHOCKING OR EMPTYING SPA TO REDUCE COMBINED CHLORINE TO .5 PPM OR BELOW.  
SAFETY EQUIPMENT OK

Free Chlorine (1.5-5.0 ppm):	<b>.8</b>	Bromine (3.0-8.0 ppm):		Temperature(Max)	<b>102</b>
Combined Chlorine (0-.5 ppm):	<b>1.2</b>	Cyanuric Acid (30-150 ppm):	<b>140</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>120</b>	Hardness (175-400 ppm):	<b>280</b>	pH (7.2-7.6):	<b>7.2</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>0</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Comments:

---

Site Report Generated: 6/19/2017 4:50:30 PM

---

Person In Charge

Inspection By: Mason Lyman

**Historical 10/16/2013**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: SEMI  
Inspection Result: COMPLD  
Establishment #: 2950036A Area: 62  
Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Melissa Kauffman

Start Date/Time: 10/16/2013 at 12:05:43 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.

- GOOD ENCLOSURE SECURITY
- GOOD CLAIRTY
- GOOD SIGNS FOR PATRON SECURITY
- PROPER SAFETY EQUIPMENT IN PLACE
- RAILINGIS SECURE
- SKIMMERS ARE CLEAN
- TWO PUMPS IN PUMP ROOM PUMP #1 60GPM PUMP #2 20GPM FLOW RATE- GOOD TURNOVER
- GOOD RECORD KEEPING
- GOOD DEMONSTRATION OF KNOWLEDGE

Free Chlorine (1.5-5.0 ppm):	<b>18.</b>	Bromine (3.0-8.0 ppm):	Temperature(Max)	<b>102</b>
Combined Chlorine (0-.5 ppm):	<b>.1</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>60</b>	Hardness (175-400 ppm):	pH (7.2-7.6):	<b>7.3</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:	<b>0</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

Establishment: 2950036A

Page 12 of 14

Inspection Type: SEMI

Start Date/Time: 10/16/2013 at 12:05:43

\*DISCUSSED EMERGENCY PHONE WITH PIC

---

Site Report Generated: 6/19/2017 4:50:30 PM

---

Person In Charge

Inspection By: Melissa Kauffman

Page 12

**Historical 5/17/2013**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: SEMI  
Inspection Result: COMPLD  
Establishment #: 2950036A Area: 62

Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Melissa Kauffman

Start Date/Time: 5/17/2013 at 11:51:55 AM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSEPCION

CLARITY IS GOOD  
ENCLOSURE IS GOOD  
RECORD KEEPING IS GOOD  
PUMP ROOM HAS ALL NECESSARY SAFETY EQUIPMENT

PH IS ALMOST TOO HIGH PLEASES KEEP LEVEL BELOW 7.6 PREFERABLY CLOSER TO 7.2

Free Chlorine (1.5-5.0 ppm):	<b>1.6</b>	Bromine (3.0-8.0 ppm):	Temperature(Max)	<b>102</b>
Combined Chlorine (0-.5 ppm):	<b>.1</b>	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):		Hardness (175-400 ppm):	pH (7.2-7.6):	<b>7.6</b>
Inlet Pressure:		Outlet Pressure:	Flow Rate:	<b>.40</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):				

FLOW RATE IS ABOUT EVERY 15 MIN  
OVERALL SPA IS IN GOOD CONDITION THANK YOU

---

Site Report Generated: 6/19/2017 4:50:30 PM

**Historical 11/28/2012**

**SPA INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
MHC TT, INC DBA PACIFIC CITY  
PACIFIC CITY - SPA  
30000 SANDLAKE RD  
CLOVERDALE, OR 97112

Inspection Type: SEMI  
Inspection Result: COMPLD  
Establishment #: 2950036A Area: 62  
Units: 0  
County: 29

PACIFIC CITY - SPA  
PO BOX 8000  
MONSEY, NY 10952

Phone: (503) 965-6442 x  
Inspector: Annette Pampush

Start Date/Time: 11/28/2012 at 9:37:52 AM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

ATTEMPTED TO INSPECT, SPA CLOSED FOR THE SEASON. SPA IS NOW CLOSED IN OCTOBER, OPENING IN MARCH

Free Chlorine (1.5-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(Max
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (30-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		

Comments:

---

Site Report Generated: 6/19/2017 4:50:30 PM

Person In Charge

Inspection By: Annette Pampush