

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943

Owner Name:

WON KIM

SUNSET SURF MOTEL - POOL

248 OCEAN ROAD

MANZANITA, OR 97130

Inspection Type: ANNUAL

Inspection Result: COMPLD

Establishment #: 2940006A Area: 60

Units: 0

County: 29

SUNSET SURF MOTEL - POOL

PO BOX 458

MANZANITA, OR 97130

Phone: (503) 368-5224 x

Inspector: Jaime Craig

Start Date/Time: 9/20/2016 at 4:24:48 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

ATTEMPTED TO INSPECT BUT POOL IS CLOSED FOR THE YEAR. RE-OPENS JUNE 2017

Free Chlorine (0.8-5.0 ppm):

Bromine (3.0-8.0 ppm):

Temperature(F):

Combined Chlorine (0-.5 ppm):

Cyanuric Acid (0-150 ppm):

Clarity (Y/N):

Total Alkalinity (80-200 ppm):

Hardness (175-400 ppm):

pH (7.2-7.6):

Inlet Pressure:

Outlet Pressure:

Flow Rate:

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

Comments:

Site Report Generated: 6/23/2017 9:49:25 AM

Person In Charge

Inspection By: Jaime Craig

**Historical 9/8/2015 POOL PROGRAM INSPECTION REPORT** Page 2 of 9

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
WON KIM

SUNSET SURF MOTEL - POOL  
248 OCEAN ROAD  
MANZANITA, OR 97130

Inspection Type: ANNUAL  
Inspection Result: COMPLD  
Establishment #: 2940006A Area: 60

Units: 0  
County: 29

SUNSET SURF MOTEL - POOL  
PO BOX 458  
MANZANITA, OR 97130

Phone: (503) 368-5224 x  
Inspector: Mason Lyman

Start Date/Time: 9/8/2015 at 3:06:58 PM

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

ANNUAL INSPECTION OF POOL-  
20,000 GALLON POOL  
GOOD TURNOVER- LESS THAN 8 HOURS.  
DECK SURFACE REPAIRED FROM LAST INSPECTION.  
STAIRS/LADDERS OK  
ENCLOSURE OK  
CHEMICALS/ROOMS OK  
PHONE SIGN UP

Free Chlorine (0.8-5.0 ppm):	<b>4.4</b>	Bromine (3.0-8.0 ppm):		Temperature(F):	<b>87</b>
Combined Chlorine (0-.5 ppm):	<b>0.2</b>	Cyanuric Acid (0-150 ppm):	<b>200</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>90</b>	Hardness (175-400 ppm):	<b>270</b>	pH (7.2-7.6):	<b>7.0</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>55</b>

ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):

333-060-0105(2)(f.2)

VIOLATION OF OAR 333-060-0105 (2)(f) The door or gate swings inward into the pool area.

**DOOR OPENS INWARD.**

Change the swing of the door or gate to swing outwards away from the pool. This increases the safety of the door or gate significantly.

**PLEASE CHANGE DIRECTION OF DOOR.**

333-060-0200(3)(4)

VIOLATION OF OAR 333-060-0200 (3) & (4) The pool water quality parameters are not tested at the required frequencies or are not recorded.

**FACILITY IS NOT CHECKING COMBINED CHLORINE.**

Complete and record the required pool water tests at the minimum frequencies as described in OAR 333-060-0200 (3)(a) to (3)(j), or as required by the Division or local public health authority.

**CHECK COMBINED CHLORINE WHENEVER CHECKING FREE CHLORINE.**

Establishment: 2940006A  
Inspection Type: ANNUAL

Page 3 of 9  
Start Date/Time: 9/8/2015 at 3:06:58 PM

---

Comments:

---

Site Report Generated: 6/23/2017 9:49:26 AM

---

Person In Charge

Inspection By: Mason Lyman

Page 3

**Historical 8/29/2014**

**POOL PROGRAM INSPECTION REPORT**

Page 4 of 9

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
WON KIM  
SUNSET SURF MOTEL - POOL  
248 OCEAN ROAD  
MANZANITA, OR 97130

Inspection Type: REINSP  
Inspection Result: COMPLD  
Establishment #: 2940006A Area: 60  
Units: 0  
County: 29

SUNSET SURF MOTEL - POOL  
PO BOX 458  
MANZANITA, OR 97130

Phone: (503) 368-5224 x  
Inspector: Mason Lyman

Start Date/Time: 8/29/2014 at 11:35:44 AM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

SIGN FOR EMERGENCY PHONE INSTALLED TO GIVE LOCATION OF EMERGENCY PHONE IN OFFICE WHICH IS AVAILABLE DURING ALL POOL HOURS. CONTAINS INFORMATION FOR EMERGENCY PERSONNEL INCLUDING ADDRESS AND NAME OF FACILITY.

THEY ADDED ALKALINITY INCREASE (BAKING SODA) TO RAISE NUBMER FROM 70-110 PPM. EDUCATED EMPLOYEE ON KEEPING ALKALINITY NUMBER HIGH TO STABILIZE PH, ESPECIALLY SINCE CYANURIC ACID LEVELS ARE SO HIGH TOO.

OPERATOR TOOK CYANURIC ACID TEST, BUT DID NOT RECORD ON LOG SHEET. MENTIONED THAT LOG SHEET HAS A SPOT FOR CYA AND SHOULD BE DONE AT LEAST ONCE A MONTH.

OPERATOR DID CHLORINE TEST IN FRONT OF ME SO I COULD OBSERVE SAMPLE TECHNIQUE AND KNOWLEDGE OF TESTS, WELL DONE. OPERATOR LOWERED CHLORINE FROM EARLIER IN THE DAY AT 5 PPM, DOWN TO 1.6 PPM AT 10 AM. TALKED ABOUT HOW A CHLORINE NUMBER OF 5 PPM IS OK, THOUGHT BETWEEN 2-3 PPM WAS ONLY ACCEPTABLE VALUES. TALKED ABOUT HIGHER RATHER THAN LOWER IS BEST FOR FREE CHLORINE.

NO COMBINED CHLORINE PRESENT AT VISIT.

POOL HAS BETTER CLARITY AFTER 48 HOURS OF POOL CHEMISTRY BEING CHANGED AND BEING IN COMPLIANCE NOW.

POOL IS NOW OPEN FOR BUSINESS, WITH PH, FREE CHLORINE AND CLARITY ALL DOING WELL.

Free Chlorine (0.8-5.0 ppm):	<b>1.6</b>	Bromine (3.0-8.0 ppm):		Temperature(F):	<b>88</b>
Combined Chlorine (0-.5 ppm):	<b>0.</b>	Cyanuric Acid (0-150 ppm):	<b>120</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>110</b>	Hardness (175-400 ppm):	<b>230</b>	pH (7.2-7.6):	<b>7.2</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>0</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

Establishment: 2940006A  
Inspection Type: REINSP

Page 5 of 9  
Start Date/Time: 8/29/2014 at 11:35:44

Comments:

---

Site Report Generated: 6/23/2017 9:49:26 AM

---

Person In Charge

Inspection By: Mason Lyman

Page 5

Establishment: 2940006A  
Inspection Type: ANNUAL

Page 6 of 9  
Start Date/Time: 8/27/2014 at 1:45:25

**Historical 8/27/2014**

**POOL PROGRAM INSPECTION REPORT**

Page 6 of 9

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
WON KIM  
SUNSET SURF MOTEL - POOL  
248 OCEAN ROAD  
MANZANITA, OR 97130

Inspection Type: ANNUAL  
Inspection Result: CLOSE  
Establishment #: 2940006A Area: 60  
Units: 0  
County: 29

SUNSET SURF MOTEL - POOL  
PO BOX 458  
MANZANITA, OR 97130

Phone: (503) 368-5224 x  
Inspector: Mason Lyman

Start Date/Time: 8/27/2014 at 1:45:25 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

**OUTDOOR POOL**

SIZE ESTIMATED AT 20,000 GALLONS BY HOTEL  
FENCE OK  
SAFETY EQUIPMENT OK  
RULES POSTED AND EASY TO UNDERSTAND  
CLARITY OK  
GOOD DEPTH MARKERS AROUND POOL  
TRICHLOR USED AS DISINFECTANT

\*\*ACCORDING TO RECORDS, THEY HAVEN'T TESTED FOR CYANURIC ACID THIS SUMMER. CYA AT 120 PPM (NO VOILATION), TRICHLOR USED AS DISINFECTANT. REDUCE CYA TO GET CLOSER TO 20-50 PPM.

\*\*ALKALINITY AT 70 PPM, BUT WITH TRUE ALKALINITY RATING AT CYA =120/3= 40, 70-40=30PPM.

CALCIUM HARDNESS IS GREAT.

HOTEL VOLUNTARILY CLOSED POOL ACCORDING TO LOW CHLORINE LEVELS (0.6PPM) AND WILL REOPEN WHEN CHEMISTRY IS IN COMPLIANCE.

Free Chlorine (0.8-5.0 ppm):	<b>.6</b>	Bromine (3.0-8.0 ppm):		Temperature(F):	<b>88</b>
Combined Chlorine (0-.5 ppm):	<b>.2</b>	Cyanuric Acid (0-150 ppm):	<b>120</b>	Clarity (Y/N):	<b>Y</b>
Total Alkalinity (80-200 ppm):	<b>70</b>	Hardness (175-400 ppm):	<b>260</b>	pH (7.2-7.6):	<b>7.0</b>
Inlet Pressure:		Outlet Pressure:		Flow Rate:	<b>0</b>
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):					

333-060-0110(8)

VIOLATION OF OAR 333-060-0110 (8) Adjoining deck surface elevations vary by more than 1/4 inch (6 mm).

**DECK SURFACE AT NORTHEAST CORNER OF DEEP PART OF POOL HAS A 1 INCH RISE.**

Construct or repair the deck so that adjoining deck surface elevations vary no more than 1/4 inch (6mm) to prevent tripping hazards..

**REDUCE TRIP HAZARDS BY ELIMINATING GAPS ALONG JOINTS TO 1.4 INCH.**

Establishment: 2940006A

Page 7 of 9

Inspection Type: ANNUAL

Start Date/Time: 8/27/2014 at 1:45:25

333-060-0210(2)

VIOLATION OF OAR 333-060-0210 (2) No telephone, or other acceptable means to reach emergency assistance is accessible, or directions to the telephone are not provided.

**NO EMERGENCY PHONE IN POOL AREA**

Provide a telephone that is accessible at all times the pool is open. The telephone must be capable of reaching emergency assistance without the use of coins or cards. Conspicuously post the location of the phone in the pool area.

The phone should b

**PROVIDE EMER PHONE OR DIRECTIONS TO PHONE WITH EMERGENCY INFORMATION.**

Comments:

---

Site Report Generated: 6/23/2017 9:49:26 AM

---

Person In Charge

Inspection By: Mason Lyman

Page 7

Establishment: 2940006A  
Inspection Type: ANNUAL

Start Date/Time: 8/21/2013 at 1:36:28

**Historical 8/21/2013**

**POOL PROGRAM INSPECTION REPORT**

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141  
(503) 842-3943**

Owner Name:  
WON KIM

SUNSET SURF MOTEL - POOL  
248 OCEAN ROAD  
MANZANITA, OR 97130

Inspection Type: ANNUAL  
Inspection Result: COMPLD  
Establishment #: 2940006A Area: 60

Units: 0  
County: 29

SUNSET SURF MOTEL - POOL  
PO BOX 458  
MANZANITA, OR 97130

Phone: (503) 368-5224 x  
Inspector: Melissa Kauffman

Start Date/Time: 8/21/2013 at 1:36:28 PM

---

NOTICE OF INSPECTION: AN INSPECTION OF THE ABOVE-NAMED FACILITY WAS CONDUCTED ON THIS DATE TO ASCERTAIN COMPLIANCE WITH OR 448.005- 448.090 AND RULES OF THE OREGON HEALTH AUTHORITY PERTAINING TO PUBLIC SWIMMING POOLS AND PUBLIC SPA POOLS. FAILURE TO CORRECT ITEMS LISTED BELOW MAY RESULT IN SUSPENSION, REVOCATION OR DENIAL OF THE PERMIT OR LICENSE ISSUED UNDER ORS 448.030 or 448.035.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION

TEMPERATURE 84F  
FREE CHLORINE 1.8  
COMBINED 0PPM  
PH 7  
CALCIUM HARDNESS 190  
CYANURIC ACID 70

GREAT RECORD KEEPING  
FLOW METER READS 120GPM

FENCES AND GATES ARE SECURE  
WINDOW AND GLASS ARE SECURE  
DECK EQUIPMENT IS IN GOOD CONDITION  
\*ROUND LIFE SAVER IS MISSING A ROPE TO PULL  
LADDER IS SECURE  
DEPTH MARKER IS CLEAR  
DECK SUFACE IS CLEAN  
SKIMMERS ARE CLEAN  
LIGHTS ARE ADEQUATELY MAINTAINED  
SAFETY EQUIPMENT IS PROVIDED  
POOL IS NEXT TO OFFICE WITH EMERGENCY PHONE  
TEST KIT AVAILABLE

Free Chlorine (0.8-5.0 ppm):	Bromine (3.0-8.0 ppm):	Temperature(F):
Combined Chlorine (0-.5 ppm):	Cyanuric Acid (0-150 ppm):	Clarity (Y/N):
Total Alkalinity (80-200 ppm):	Hardness (175-400 ppm):	pH (7.2-7.6):
Inlet Pressure:	Outlet Pressure:	Flow Rate:
ORP mVolts (750 mVolts for Cl- and 700 mVolts for Br-):		



Establishment: 2940006A  
Inspection Type: ANNUAL

Page 9 of 9  
Start Date/Time: 8/21/2013 at 1:36:28

Comments:

---

Site Report Generated: 6/23/2017 9:49:26 AM

---

Person In Charge

Inspection By: Melissa Kauffman

Page 9