Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141 (503) 842-3943

Owner Name:

TILLAMOOK RV PARK LLC

TILLAMOOK RV PARK

1950 SUPPRESS RD N

Inspection Type: SEMI
Inspection Result: COMPLD

TILLAMOOK, OR 97141 Establishment #: 2920096B Area: 31

Units: 31 County: 29

TILLAMOOK RV PARK 466 FOOTHILL BLVD #387 LA CANADA, CA 91011

Phone: (503) 354-4627 x

Inspector: Jaime Craig

Start Date/Time: 1/13/2017 at 12:09:51 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

PERSON IN CHARGE EASILY FOUND (CAMP HOST)

DUMPSTER AND GARBAGE CANS IN TENT RV AREA, TENT, AREA, AND BBQ AREA, CLEAN AND EMPTY. GOOD SPACING BETWEEN SITES-10FT GROUNDS CLEAN AND WELL MAINTAINED BATHROOMS CLEAN-WINDOWS SCREENED, MEN'S BATHROOM HAS SIGN THAT SAYS "BEING REMODELED"

PARK HAS GOOD NUMBER OF RV'S ON SITE

RV HOOK-UP WATER SOURCES SITE #07,12,29 ARE LEAKING WATER.

SITES #8, 19 MISSING BACKFLOW PREVENTION DEVICES.

NO EVIDENCE OF RODENTS

SITES CLEARLY MARKED

LAUNDRY ROOM CLEAN- ONE WINDOW SCREENED, ONE NOT, BUT LOOKS LIKE IT DOESN'T"T GET OPENED.

SEWER SLOPED FOR PROPER DRAINAGE. OUTSIDE OF BUILDING LOOK GOOD AND MAINTAINED. "PETTING ZOO ON SITE" RULES UP AND REMINDED STAFF TO DISPLAY "HAND WASH" AFTER TOUCHING ANIMALS

333-031-0008(1)

Violation of OAR 333-031-0008 (1) Insect and rodent control measures are not effective in protecting the public health, preventing a nuisance to the public or accumulations of debris are noted.

GAP AT BOTTOM OF WOMAN'S RESTROOM DOOR.

Apply insect and rodent control measures, including maintenance of developed areas, buildings and structures, to be free of accumulating debris, to prevent nuisance to the public and to safeguard the public health.

PLEASE ADD STRIP TO CLOSE THE GAP.

Comments:

Site Report Generated: 6/23/2017 3:43:15 PM

Establishment: 2920096B Page 2 of 6

Inspection Type: SEMI Start Date/Time: 8/22/2016 at 3:55:32

Historical 8/22/2016 RECREATIONAL PARK INSPECTION REPORT

Page 2 of 6

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141 (503) 842-3943

Owner Name:

TILLAMOOK RV PARK LLC

TILLAMOOK RV PARK

1950 SUPPRESS RD N

Inspection Type: SEMI
Inspection Result: COMPLD

TILLAMOOK, OR 97141 Establishment #: 2920096B Area: 31

Units: 31 County: 29

TILLAMOOK RV PARK
466 FOOTHILL BLVD #387
LA CANADA, CA 91011

Phone: (503) 354-4627 x
Inspector: Jaime Craig

Start Date/Time: 8/22/2016 at 3:55:32 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

PERSON IN CHARGE ON SITE

DUMPSTER AND GARBAGE CANS IN TENT RV AREA, TENT, AREA, AND BBQ AREA, CLEAN AND EMPTY. GOOD SPACING BETWEEN SITES-10FT

GROUNDS CLEAN AND WELL MAINTAINED

BATHROOMS CLEAN-WINDOWS SCREENED, MEN;S BATHROOM HAS SIGN THAT SAYS "BEING REMODLED"

PARK HAS GOOD NUMBER OF RV"S ON SITE

RV HOOK-UP WATER SOURCES SITE 06,23,32 ARE LEAKING.

SITES 1,17,21,29 AND 24 MISSING BACKFLOW PREVENTION DEVICES.

NO EVIDENCE OF RODENTS

SITES CLEARLY MARKED

LAUNDRY ROOM CLEAN- ONE WINDOW SCREENED, ONE NOT, UT LOOKS LIKE IT DOESN"T GET OPENED.

SEWER SLOPED FOR PROPER DRAINAGE.

OUTSIDE OF BUILDING LOOK GOOD AND MAINTAINED.

THANK YOU!

| Establishment: 2920096B | | | | Page 3 of 6 |
|-------------------------|----------------------|----------------|------------------|----------------------|
| Inspection Type: SEMI | | | Start Date/Time: | 8/22/2016 at 3:55:32 |
| Comments: | | | | |
| Site Report Generated: | 6/23/2017 3:43:15 PM | | | |
| | | | | |
| Person In Charge | | Inspection By: | Jaime Craig | Page 3 |

Establishment: 2920096B Page 4 of 6

Inspection Type: SEMI Start Date/Time: 1/6/2016 at 12:44:28

Historical 1/6/2016 RECREATIONAL PARK INSPECTION REPORT

Page 4 of 6

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141 (503) 842-3943

Owner Name:

TILLAMOOK RV PARK LLC

TILLAMOOK RV PARK

1950 SUPPRESS RD N

Inspection Type: SEMI
Inspection Result: COMPLD

TILLAMOOK, OR 97141 Establishment #: 2920096B Area: 31

Units: 31 County: 29

TILLAMOOK RV PARK
466 FOOTHILL BLVD #387
LA CANADA, CA 91011

Phone: (503) 354-4627 x
Inspector: Mason Lyman

Start Date/Time: 1/6/2016 at 12:44:28 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

INSPECTION OF RV PARK-

RESTROOMS CLEAN/WELL MAINTAINED
SCREENS ON WINDOWS IN RESTROOM/LAUNDRY ROOM
SHELVING MADE OF NON-ABSORBENT MATERIALS
OUTSIDE OF BUILDINGS WELL MAINTAINED
SITES EASILY IDENTIFIABLE
GOOD FLOW OF TRAFFIC AROUND PARK
PICNIC TABLES IN GOOD SHAPE
SEWER LINES PROPERLY SLOPED TO DRAIN
NO LEAKS DETECTED AT PARK

| NO VIOLATIONS- THANK | YOU | | | |
|------------------------|----------------------|----------------|-------------|--------|
| Site Report Generated: | 6/23/2017 3:43:15 PM | | | |
| Person In Charge | | Inspection By: | Mason Lyman | Page 4 |

Establishment: 2920096B Page 5 of 6

Inspection Type: SEMI Start Date/Time: 7/1/2015 at 1:37:41 PM

Historical

7/1/2015

RECREATIONAL PARK INSPECTION REPORT

Page 5 of 6

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141 (503) 842-3943

Owner Name:

TILLAMOOK RV PARK LLC

TILLAMOOK RV PARK

1950 SUPPRESS RD N

Inspection Type: SEMI
Inspection Result: COMPLD

TILLAMOOK, OR 97141 Establishment #: 2920096B Area: 31

Units: 31 County: 29

TILLAMOOK RV PARK
466 FOOTHILL BLVD #387
LA CANADA, CA 91011

Phone: (503) 354-4627 x
Inspector: Mason Lyman

Start Date/Time: 7/1/2015 at 1:37:41 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

SEMIANNUAL INSPECTION OF FACILITY-

BACKFLOW PREVENTERS ON FAUCETS
MOST SEWER LINES SLOPED WELL
GARBAGE REMOVED OFTEN/ DONE SAFELY
GOOD OVERALL MAINTENANCE TO PARK
GOOD FLOW OF TRAFFIC
SITES IDENTIFIED EASILY BY EMERGENCY PERSONNEL
PICNIC TABLES IN GOOD REPAIR
PIC EASILY FOUND ON SITE
RESTROOMS CLEAN/ STOCKED
GOOD VENTILATION IN RESTROOMS/LAUNDRY ROOM

THANK YOU

^{**}SCREENS BEING PUT ON RESTROOMS/LAUNDRY ROOM CURRENTLY.

^{**}SITE #7 HAS IMPROPERLY SLOPED SEWER LINE. PLEASE CORRECT THIS WEEK.

^{**}LARGE WATER LEAK COMING FROM SITE #28, PLEASE CORRECT TODAY.

Establishment: 2920096B Page 6 of 6
Inspection Type: SEMI Start Date/Time: 7/1/2015 at 1:37:41 PM

| Comments: | | | | |
|------------------------|----------------------|----------------|-------------|--------|
| Site Report Generated: | 6/23/2017 3:43:15 PM | | | |
| | | | | |
| | | | | |
| Person In Charge | | Inspection By: | Mason Lyman | Page 6 |