

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:

JOSEPH & THERESA TAYLOR
TILLAMOOK RIVER RV PARK
85 3RD ST
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920162A Area: 31
Units: 26
County: 29

TILLAMOOK RIVER RV PARK
PO BOX 371
GARIBALDI, OR 97118

Phone: (503) 322-0052 x
Inspector: Jaime Craig

Start Date/Time: 9/13/2016 at 9:53:22 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

PERSON IN CHARGE EASILY FOUND
DUMP STATION CLEAN
GARBAGE SERVICE TWICE A WEEK
PARK AND BUILDINGS CLEAN AND MAINTAINED
PICNIC TABLES AND FIRE PITS IN GOOD REPAIR
GOOD FLOW OF TRAFFIC THROUGH PARK
SITES EASILY IDENTIFIABLE
NO EVIDENCE OF INSECTS OR RODENTS
RESTROOMS CLEAN, VENTILATED, AND STOCKED

THANKS!

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

BACK FLOW PREVENTERS MISSING ON MOST SITES

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

PLEASE HAVE BACKFLOW PREVENTORS ON ALL SITES.

Comments:

Site Report Generated: 6/23/2017 2:32:15 PM

Historical 1/6/2016 RECREATIONAL PARK INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

JOSEPH & THERESA TAYLOR
TILLAMOOK RIVER RV PARK
85 3RD ST
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920162A Area: 31

Units: 26
County: 29

TILLAMOOK RIVER RV PARK
PO BOX 371
GARIBALDI, OR 97118

Phone: (503) 322-0052 x
Inspector: Mason Lyman

Start Date/Time: 1/6/2016 at 10:18:49 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

INSPECTION OF RV PARK-

DUMP STATION CLEAN
RESTROOM CLEAN/WELL MAINTAINED
GOOD VENTILATION IN RESTROOMS
GOOD SPACING OF SITES- MORE THAN 10 FEET
GOOD FLOW OF TRAFFIC AROUND PARK

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

BACKFLOW PREVENTERS MISSING ON MOST FAUCETS.

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

PLEASE CORRECT.

**PAINT IS CHIPPING AWAY IN WOEMSN SHOWER STALL, PLEASE CORRECT.
PLEASE FRESHEN UP SITES ID'S TO MAKE IT EASIER TO IDENTIFY.

Site Report Generated: 6/23/2017 2:32:15 PM

Historical 7/1/2015 RECREATIONAL PARK INSPECTION REPORT Page 3 of 8

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
JOSEPH & THERESA TAYLOR
TILLAMOOK RIVER RV PARK
85 3RD ST
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920162A Area: 31
Units: 26
County: 29

TILLAMOOK RIVER RV PARK
PO BOX 371
GARIBALDI, OR 97118

Phone: (503) 322-0052 x
Inspector: Mason Lyman
Start Date/Time: 7/1/2015 at 3:39:01 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

SEMIANNUAL INSPECTION OF PARK-

- MOST SEWER LINES SLOPED WELL
- GARBAGE COLLECTION SAFE/ DONE TWICE A WEEK.
- PICNIC TABLES IN GOOD REPAIR
- PIC ONSITE EASILY FOUND
- SITES EASILY IDENTIFIABLE
- GOOD FLOW OF TRAFFIC AROUND PARK
- RESTROOMS CLEAN/WELL MAINTAINED
- GOOD VENTILATION IN RESTROOMS.

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

BACKFLOW PREVENTERS MISSING ON MOST FAUCETS

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

PLEASE CORRECT.

Comments:

Site Report Generated: 6/23/2017 2:32:15 PM

Historical 1/9/2015 RECREATIONAL PARK INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
JOSEPH & THERESA TAYLOR
TILLAMOOK RIVER RV PARK
85 3RD ST
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920162A Area: 31
Units: 26
County: 29

TILLAMOOK RIVER RV PARK
PO BOX 371
GARIBALDI, OR 97118

Phone: (503) 322-0052 x
Inspector: Mason Lyman
Start Date/Time: 1/9/2015 at 3:50:46 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

SEMIANNUAL INSPECTION OF PARK-

- MOST SEWER LINES SLOPED CORRECTLY
- GOOD SPACING BETWEEN RV'S (MORE THAN 10FEET)
- SITES EASILY IDENTIFIED
- GARBAGE COLLECTION DONE WELL/ OFF THE GROUND AND COVERED.
- PICNIC TABLES IN GOOD REPAIR
- GOOD FLOW OF TRAFFIC/ NO BLOCKAGES
- RESTROOMS WELL VENTED, HOT WATER PRESENT
- SURFACES ARE SMOOTH AND EASILY CLEANABLE

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

VERY FEW BACKFLOW PREVENTERS INSTALLED IN PARK.

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

PLEASE CORRECT.

Comments:

Site Report Generated: 6/23/2017 2:32:15 PM

Establishment: 2920162A

Page 5 of 8

Inspection Type: SEMI

Start Date/Time: 7/30/2014 at 1:04:29

Historical 7/30/2014 RECREATIONAL PARK INSPECTION REPORT

Page 5 of 8

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

JOSEPH & THERESA TAYLOR
TILLAMOOK RIVER RV PARK
85 3RD ST
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920162A Area: 31

Units: 26
County: 29

TILLAMOOK RIVER RV PARK
PO BOX 371
GARIBALDI, OR 97118

Phone: (503) 322-0052 x
Inspector: Mason Lyman

Start Date/Time: 7/30/2014 at 1:04:29 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

A CENTRAL DUMP SITE USED FOR ALL SITES, NO SEWAGE LINES AT EACH SPACE.
RESTROOMS LOOKED GOOD.
NO CENTRAL LAUNDRY SERVICES AVAILABLE.
PARK CLEAN, WELL MAINTAINED AND LANDSCAPED.

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

BACKFLOW PREVENTION DEVICES NOT INSTALLED

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

Comments:

Site Report Generated: 6/23/2017 2:32:15 PM

Person In Charge

Inspection By: Mason Lyman

Page 5

Historical 1/24/2014 RECREATIONAL PARK INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
JOSEPH & THERESA TAYLOR
TILLAMOOK RIVER RV PARK
85 3RD ST
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920162A Area: 31
Units: 26
County: 29

TILLAMOOK RIVER RV PARK
PO BOX 371
GARIBALDI, OR 97118

Phone: (503) 322-0052 x
Inspector: Alex Manderson

Start Date/Time: 1/24/2014 at 1:39:42 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

Semi-Annual inspection.

Men's and ' bathrooms are dry and clean.

Soap, paper towels and hot and cold running water provided in both.

Ventilation fans operate when shower is on.

All R.V sites tidy and well marked. Trash dumpster clean.

No individual site sewage connections. Sewage is dumped at single dump station adjacent to bathrooms as needed. 1,500 gal sewage tank here is pumped out when full. Fitted with alarm system to prevent overflow.

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

Anti-siphon connections missing from water lines at R.V sites.

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

Comments:

Site Report Generated: 6/23/2017 2:32:15 PM

Establishment: 2920162A

Page 7 of 8

Inspection Type: SEMI

Start Date/Time: 7/30/2013 at 8:28:31

Historical 7/30/2013 RECREATIONAL PARK INSPECTION REPORT

Page 7 of 8

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

JOSEPH & THERESA TAYLOR
TILLAMOOK RIVER RV PARK
85 3RD ST
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920162A Area: 31

Units: 26
County: 29

TILLAMOOK RIVER RV PARK
PO BOX 371
GARIBALDI, OR 97118

Phone: (503) 322-0052 x
Inspector: Melissa Kauffman

Start Date/Time: 7/30/2013 at 8:28:31 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION.

GROUNDS IN GOOD REPAIR
NO SEWAGE LINES AT INDIVIDUAL CAMP SITES
RESTROOMS ARE LOCKED
CAMP SITES ARE EASILY IDENTIFIABLE
CAMPERS ARE 10FT APART

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

ALL WATER SPIGOTS ARE MISSING BACKFLOW PREVENTORS AT THE SOURCE

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

A BACKFLOW PREVENTOR IS REQUIRED AT ALL INDIVIDUAL RV SITES

Comments:

Site Report Generated: 6/23/2017 2:32:15 PM

Person In Charge

Inspection By: Melissa Kauffman

Page 7

Establishment: 2920162A

Page 8 of 8

Inspection Type: SEMI

Start Date/Time: 1/29/2013 at 2:16:09

Historical 1/29/2013 RECREATIONAL PARK INSPECTION REPORT

Page 8 of 8

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

JOSEPH & THERESA TAYLOR
TILLAMOOK RIVER RV PARK
85 3RD ST
TILLAMOOK, OR 97141

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920162A Area: 31

Units: 26
County: 29

TILLAMOOK RIVER RV PARK
PO BOX 371
GARIBALDI, OR 97118

Phone: (503) 322-0052 x
Inspector: Melissa Kauffman

Start Date/Time: 1/29/2013 at 2:16:09 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSEPCTION OF THE RV PARK

RESTOOM IS IN GOOD REPAIR SOME PAINT NEEDED
ALL WATER SPIGOTS THAT WERE CHECKED HAVE MISSING BACKFLOW PREVENTORS
NO SEWAGE LINES ARE AT SITES
OVERALL GROUNDS ARE IN GOOD REPAIR.

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

BACK FLOW PREVENTORS ARE MISSING FROM WATER SPIGOTS

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

PIC SAYS THAT THERE IS A LINE IN THE SYSTEM THAT HAS BACKFLOW

Comments:

Site Report Generated: 6/23/2017 2:32:15 PM

Person In Charge

Inspection By: Melissa Kauffman

Page 8