

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943

Owner Name:

WINEMA CHRISTIAN CAMP
WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD.
CLOVERDALE, OR 97112

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920198 Area: 31
Units: 32
County: 29

WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD
CLOVERDALE, OR 97112

Phone: (503) 392-3362 x
Inspector: Jaime Craig

Start Date/Time: 1/9/2017 at 10:55:26 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THIS IS A SEMI ANNUAL INSPECTION OF THE PARK.
32 (TECHNICALLY) SPACES (ONE SPACE OCCUPIED CURRENTLY)
2A LEAKING WATER-NOTIFIED STAFF
BACKFLOW PREVENTERS ON ALL FAUCETS-THANK YOU
DUMPSTER SECURE AND NO EVIDENCE OF RODENTS
RECYCLE AREA CLEAN
BATHROOMS INSIDE FACILITIES CLEAN, HOT WATER
NO LAUNDRY ON SITE FOR GUESTS

Comments:

Site Report Generated: 6/20/2017 8:11:24 AM

Person In Charge

Inspection By: Jaime Craig

Establishment: 2920198

Page 2 of 8

Inspection Type: SEMI

Start Date/Time: 7/26/2016 at 11:04:59

Historical 7/26/2016

RECREATIONAL PARK INSPECTION REPORT

Page 2 of 8

Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141

(503) 842-3943

Owner Name:

WINEMA CHRISTIAN CAMP

WINEMA CHRISTIAN CAMP RV PARK

5195 WI-NE-MA RD.

CLOVERDALE, OR 97112

Inspection Type: SEMI

Inspection Result: COMPLD

Establishment #: 2920198 Area: 31

Units: 32

County: 29

WINEMA CHRISTIAN CAMP RV PARK

5195 WI-NE-MA RD

CLOVERDALE, OR 97112

Phone: (503) 392-3362 x

Inspector: Annette Pampush

Start Date/Time: 7/26/2016 at 11:04:59 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THIS IS A SEMI ANNUAL INSPECTION

PARK IS PARTIALLY OCCUPIED

NEW WATER SPIGOTS HAVE BEEN INSTALLED- NO BACKFLOW PREVENTORS ARE ON THEM. THIS IS BEING LOOKED INTO TO BE ABLE TO GET PREVENTORS THAT WILL WORK

NI EW ELECTRICAL BOXES INSTALLED AS WELL

SEWER CONNECTIONS ALL LOOK OKAY

GROUNDS CLEAN AND WELL MAINTAINED

THANKS

Comments:

Site Report Generated: 6/20/2017 8:11:25 AM

Person In Charge

Inspection By: Annette Pampush

Page 2

Establishment: 2920198

Page 3 of 8

Inspection Type: SEMI

Start Date/Time: 3/15/2016 at 10:34:50

Historical 3/15/2016 RECREATIONAL PARK INSPECTION REPORT

Page 3 of 8

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

WINEMA CHRISTIAN CAMP
WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD.
CLOVERDALE, OR 97112

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920198 Area: 31

Units: 32
County: 29

WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD
CLOVERDALE, OR 97112

Phone: (503) 392-3362 x
Inspector: Mason Lyman

Start Date/Time: 3/15/2016 at 10:34:50 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

SEMIANNUAL INSPECTION OF FACILITY-

BACKFLOW PREVENTERS ON MOST FAUCETS
SEWER LINES SLOPED CORRECTLY
GARBAGE COLLECTION AREA PROTECTED
PICNIC TABLES IN GOOD REPAIR
CAMPING SITES EASILY READABLE
GOOD SPACING BETWEEN CAMPING VEHICLES
EXTERIOR OF BUILDINGS IN GOOD REPAIR
NO EVIDENCE OF RODENTS/PESTS IN FACILITY

Comments:

Site Report Generated: 6/20/2017 8:11:25 AM

Person In Charge

Inspection By: Mason Lyman

Page 3

Establishment: 2920198

Page 4 of 8

Inspection Type: SEMI

Start Date/Time: 8/12/2015 at 12:07:04

Historical 8/12/2015 RECREATIONAL PARK INSPECTION REPORT

Page 4 of 8

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

WINEMA CHRISTIAN CAMP
WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD.
CLOVERDALE, OR 97112

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920198 Area: 31
Units: 32
County: 29

WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD
CLOVERDALE, OR 97112

Phone: (503) 392-3362 x
Inspector: Mason Lyman

Start Date/Time: 8/12/2015 at 12:07:04 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

BACKFLOW PREVENTERS ON MOST FAUCETS
SEWER LINES PROPERLY SLOPED
GOOD FLOW OF TRAFFIC AROUND PARK
NO EVIDENCE OF RODENTS/PESTS
OUTSIDE OF BUILDINGS IN GOOD REPAIR
RESTROOMS CLEAN
GARBAGE COLLECTION AREA SAFE/OFF THE GROUND

****KEEP IN MIND FOR REMODEL TO KEEP CAMPING VEHICLES AT LEAST 10 FEET AWAY FOR PRIVACY AND SAFETY CONCERNS.**

Comments:

Site Report Generated: 6/20/2017 8:11:25 AM

Person In Charge

Inspection By: Mason Lyman

Page 4

Historical 1/21/2015 RECREATIONAL PARK INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:
WINEMA CHRISTIAN CAMP
WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD.
CLOVERDALE, OR 97112

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920198 Area: 31
Units: 32
County: 29

WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD
CLOVERDALE, OR 97112

Phone: (503) 392-3362 x
Inspector: Mason Lyman

Start Date/Time: 1/21/2015 at 11:36:49 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

SEMIANNUAL INSPECTION OF RV PARK-

RESTROOMS CLEAN AND MADE OF SMOOTH SURFACES, HOT WATER WORKING
SITES HAVE CLEAR NUMBERS INDICATING POSITION IN PARK.
SEWER LINES PROPERLY SLOPED TO ALLOW DRAINAGE.
RV SPOTS ARE MORE THAN 10 FEET APART FROM EACH OTHER

ELECTRICITY IS CLEAN
GOOD FLOW OF TRAFFIC AROUND PARK
GARBAGE COLLECTION DONE SAFELY, PROTECTED AND OFF THE GROUND.

**CHECK VENTILATION IN RESTROOMS AND HOW AND WHEN VENTS TURN ON.

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

BACKFLOW PREVENTERS MISSING ON ABOUT 10 OUTLETS.

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

PLEASE INSTALL TO REDUCE CHANCE OF BACK SIPHONING IN WATER SYSTEM.

Comments:

Site Report Generated: 6/20/2017 8:11:25 AM

Historical 8/11/2014 RECREATIONAL PARK INSPECTION REPORT

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

WINEMA CHRISTIAN CAMP
WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD.
CLOVERDALE, OR 97112

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920198 Area: 31

Units: 32
County: 29

WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD
CLOVERDALE, OR 97112

Phone: (503) 392-3362 x
Inspector: Mason Lyman

Start Date/Time: 8/11/2014 at 11:03:13 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THIS IS THE SEMI ANNUAL INSPECTION.

- SPACES LABELED CORRECTLY AND CLEARLY.
- RV SPOTS AT LEAST 10 FEET APART.
- ROADS CLEAR TO ALLOW TRAFFIC TO FLOW.
- ELECTRICITY HOOKUP WERE CLEAN.
- RESTROOMS ARE CLEAN AND FUNCTIONING.
- GARBAGE DISPOSAL LOCATIONS KEPT CLEAN AND INSTALLED TO AVOID CONTAMINATION.

**FIXED A SEWER LINE THAT WAS IMPROPERLY SLOPED.

333-031-0004(4)

Violation of OAR 333-031-0004 (4) The plumbing system is not in compliance with the applicable provisions of the Oregon Plumbing Specialty Code.

SEVERAL (10 SPIGOTS) WERE WITHOUT BACKFLOW PREVENTION DEVICES.

Bring the plumbing into compliance with the Oregon Plumbing Specialty Code. Specifically:

INSTALL BACKFLOW DEVICES ON ALL WATER OUTLETS.

Comments:

Site Report Generated: 6/20/2017 8:11:25 AM

Establishment: 2920198

Page 7 of 8

Inspection Type: SEMI

Start Date/Time: 7/29/2013 at 10:04:52

Historical 7/29/2013 RECREATIONAL PARK INSPECTION REPORT

Page 7 of 8

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

WINEMA CHRISTIAN CAMP
WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD.
CLOVERDALE, OR 97112

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920198 Area: 31
Units: 32
County: 29

WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD
CLOVERDALE, OR 97112

Phone: (503) 392-3362 x
Inspector: Melissa Kauffman

Start Date/Time: 7/29/2013 at 10:04:52 AM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION OF THE RV PARK
THE CAMP IS FULL
ALL SITES ARE EASILY IDENTIFIABLE
ALL SITES HAVE BACKFLOW PREVENTORS
ALL SEWAGE LINES ARE PROPERLY SLOPED
MAJORITY OF CAMPER HAVE 10FT OF SPACING BETWEEN THEM
NO CLUTTER OR UNECESSARY GARBAGE
GROUNDS ARE IN GOOD REPAIR
RESTROOMS AND SHOWER ARE IN GOOD CONDITION

DISCUSSED THE ABUNDANCE OF TENTS AT THE CAMP GROUNDS WITH PIC.

Site Report Generated: 6/20/2017 8:11:25 AM

Person In Charge

Inspection By: Melissa Kauffman

Page 7

Establishment: 2920198

Page 8 of 8

Inspection Type: SEMI

Start Date/Time: 1/10/2013 at 12:34:12

Historical 1/10/2013 RECREATIONAL PARK INSPECTION REPORT

Page 8 of 8

**Tillamook Co. Environmental Health PO Box 489 Tillamook, OR 97141
(503) 842-3943**

Owner Name:

WINEMA CHRISTIAN CAMP
WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD.
CLOVERDALE, OR 97112

Inspection Type: SEMI
Inspection Result: COMPLD
Establishment #: 2920198 Area: 31

Units: 32
County: 29

WINEMA CHRISTIAN CAMP RV PARK
5195 WI-NE-MA RD
CLOVERDALE, OR 97112

Phone: (503) 392-3362 x
Inspector: Melissa Kauffman

Start Date/Time: 1/10/2013 at 12:34:12 PM

AN EVALUATION OF SANITATION ON YOUR PREMISES HAS THIS DAY BEEN MADE AND YOU ARE HEREBY NOTIFIED OF THE VIOLATIONS FOUND. VIOLATIONS NOTED ON THIS REPORT MUST BE CORRECTED WITHIN THE TIME LIMIT SPECIFIED.

THE PURPOSE OF THIS VISIT IS A SEMI ANNUAL INSPECTION OF THE RV PARK

RESTROOMS ARE VERY CLEAN AND IN GOOD REPAIR
THERE IS ONE RV AT THE PARK DURING INSPECTION,
ALL WATER SPIGOTS THAT WERE CHECKED HAVE ANTI SIPHON DEVICES
GROUNDS ARE VERY CLEAN
SEWAGE LINE IS SLOPED
CAMP SITES ARE EASILY IDENTIFIABLE
GARBAGE IS PROPERLY STORED
THERE ARE NO VIOLATIONS AT THIS TIME, THANK YOU

Comments:

Site Report Generated: 6/20/2017 8:11:25 AM

Person In Charge

Inspection By: Melissa Kauffman

Page 8